



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/05/2023

User ID : JeongCH

Section A - Accident Details	
Registration Number	SG5167H
Case Reference Number	BUS/05/23/5061
Registration Date	6/5/2017
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Lam Choong Kian
Type of Accident	Side Swipe
Accident Date and Time	5/30/2023 8:34 AM
Accident Reported Date and Time	5/31/2023 8:57 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG5167H - RHS view mirror damaged XE7668S (TP) - INSURED WITH INCOME
Prepared Date and Time	5/31/2023 11:06 AM
Chassis Number	YV3S4P922HA182110
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$297.20	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$1,327.20	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	01 DAY
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	31/05/2023 11:14 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Taufikh 97495749  
WP 31/5/23 @ 2PM  
RESURVEY AFTER REPAIR  
01 DAY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/05/2023

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & REFIX FRONT RHS VIEW MIRROR			\$530.00				265		
Total Labour			\$530.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TOWING CHARGE			\$500.00				? towing receipt		
Total Other Costs			\$500.00						
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013174			MIRROR,ELECTRIC:OFF-SIDE,VOLVO B9TL,B5LH	1.00	\$412.78	10.00	\$371.50	Replace	CRA ✓
Total					\$412.78		\$371.50		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

~~YNN~~

265  
371.50  
636.50  
L/S\$500  
1 DAY #