

ASS. REC. BY:

REF:

A/G/ 730055621ky

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

05

days

Res.: \_\_\_\_\_

Yes or No

Lum Sum: \_\_\_\_\_

20

%

3 Val.: \_\_\_\_\_

Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

Got BZ

23/6

11h

2150h

Coh

Veh No: \_\_\_\_\_

S14B922J

Yr Regn: \_\_\_\_\_

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Toy Prius

C.C

1798

Colour

m Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

904286

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

JTDK1B31FU003576099

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bairun

Front

Rear

R/Bal. \_\_\_\_\_

p

mm

R/Bal. \_\_\_\_\_

p

mm

L/Bal. \_\_\_\_\_

p

mm

L/Bal. \_\_\_\_\_

p

mm

D.O.A.

30/5/23

D.O.L.

1/6/2023

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

# SMRT Accident Vehicle Repair Estimates

**SMRT Auton**  
 60 Woodland  
 FAX Number  
 Estimator Tel  
 Accident Rep  
 Date Genera  
 User ID

## Section A - Accident Details

|                                    |                                                                               |
|------------------------------------|-------------------------------------------------------------------------------|
| Registration Number                | SHB922J                                                                       |
| Case Reference Number              | TAX/05/23/2090                                                                |
| Registration Date                  | 12/12/17                                                                      |
| Company Type                       | Strides Taxi Pte Ltd                                                          |
| Make                               | TOYOTA                                                                        |
| Model                              | PRIUS4                                                                        |
| Name of Driver                     | NG PENG NAM                                                                   |
| Type of Accident                   | Head To Side                                                                  |
| Accident Date and Time             | 30/5/23 8:50 PM                                                               |
| Accident Reported Date and Time    | 31/5/23 12:10 PM                                                              |
| Is Surveyor Required?              | No                                                                            |
| Survey by                          |                                                                               |
| Vehicle is Towed Back?             | No                                                                            |
| Towed Back Date and Time           |                                                                               |
| Replacement Vehicle issued?        | No                                                                            |
| Job Card Number                    | 24118560                                                                      |
| Special Instruction to ARC, if any | HEAD TO SIDE - PLEASE CHECK RIGHT HAND PASSENGER SEAT AREA AND RIMS/TYRE AREA |
| Prepared Date and Time             | 31/5/23 2:27 PM                                                               |
| Chassis Number                     |                                                                               |
| Mileage                            |                                                                               |
| Work Shop                          |                                                                               |
| Repair Completion Date and Time    |                                                                               |

## Section B - Summary of Repair Estimates

### Summary of Repair Estimates

|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|
| Total Labour Cost            | \$1,352.00                                                                          | \$0.00                              |
| Total Spray Cost             | \$1,574.00                                                                          | \$0.00                              |
| Total Spare Part Cost        | \$6,687.79                                                                          | \$0.00                              |
| Total Other Cost             | \$1,606.88                                                                          | \$0.00                              |
| <b>TOTAL COST</b>            | <b>\$11,220.67</b>                                                                  | <b>\$0.00</b>                       |
| <b>Lump Sum Total</b>        | <b>\$11,200.00</b>                                                                  | <b>\$0.00</b>                       |
| Number of Repair Days        | 10.0                                                                                | 3 days                              |
| Prepared / Adjusted By       | Boon Chew Tay                                                                       |                                     |
| ARC / Surveyor Sign Off Date | 31/05/2023 2:49 PM                                                                  |                                     |
| Signature                    |  | Kenneth                             |
| Remarks                      |                                                                                     |                                     |

Not Authorized  
 U/Rup B

## Section C - Quotation and Accident Invoice Details

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**SMRT Accident Vehicle Repair Estimates**

 SMRT Auton  
 60 Woodland  
 FAX Number  
 Estimator Tel  
 Accident Rep

Date Genera

User ID

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

| Job Scope                 | Quotation from AR     | Adjusted by Surveyor, if applicabl |
|---------------------------|-----------------------|------------------------------------|
| TO REPAIR REAR PORTION RH | \$1,352.00 <i>700</i> |                                    |
| <b>Total Labour</b>       | <b>\$1,352.00</b>     |                                    |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC   | Adjusted by Surveyor, if applicabl |
|-------------------------------------------------|----------------------|------------------------------------|
| TO RESPRAY REAR BUMPER                          | \$378.00 <i>nn X</i> |                                    |
| TO RESPRAY RIM                                  | \$220.00 <i>600</i>  |                                    |
| TO RESPRAY REAR FENDER RH                       | \$378.00 <i>200</i>  |                                    |
| TO RESPRAY RH REAR DOOR                         | \$378.00 <i>200</i>  |                                    |
| TO RESPRAY ROCKER PANEL MOULDING                | \$220.00 <i>nn X</i> |                                    |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$1,574.00</b>    |                                    |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| Job Scope                                                    | Quotation from ARC   | Adjusted by Surveyor, if applicabl |
|--------------------------------------------------------------|----------------------|------------------------------------|
| TO WASH AND VACUUM                                           | \$60.00 <i>nn X</i>  |                                    |
| TO CHECK WIRING AND SYSTEM FUNCTION                          | \$120.00 <i>200</i>  |                                    |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                      | \$200.00 <i>300</i>  |                                    |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING                       | \$120.00 <i>600</i>  |                                    |
| TO REMOVE AND REFIT TYRE                                     | \$120.00 <i>nn X</i> |                                    |
| TO TRANSFER DOOR MECHANISM                                   | \$120.00 <i>nn X</i> |                                    |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                      | \$120.00 <i>nn X</i> |                                    |
| TO REMOVE AND REFIX UNDERCARRIAGE                            | \$350.00 <i>nn X</i> |                                    |
| TO REPLACE SUNDRY PARTS                                      | \$100.00 <i>nn X</i> |                                    |
| TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET) | \$296.88 <i>✓</i>    |                                    |
| <b>Total Other Costs</b>                                     | <b>\$1,606.88</b>    |                                    |

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number | Part Name                              | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Ap |
|-------------|---------|--------------|----------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------|
|             |         | 5215947913   | COVER, RR BUMPER ASSY                  | 1.00     | \$478.90        | 25.00        | \$359.17         | Replace <i>R</i>   | <i>X</i>    |
|             |         | 5246247030   | PAD, RR BUMPER, RH & LH, 1             | 2.00     | \$4.30          | 25.00        | \$6.45           | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5246247020   | PAD, RR BUMPER, RH & LH, 2             | 2.00     | \$4.30          | 25.00        | \$6.45           | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5246247010   | PAD, RR BUMPER, RH & LH, 3             | 2.00     | \$4.30          | 25.00        | \$6.45           | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5246147010   | PAD, RR BUMPER, CTR                    | 3.00     | \$2.50          | 25.00        | \$5.63           | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5257547040   | RETAINER, RR BUMPER, RH                | 1.00     | \$127.40        | 25.00        | \$95.55          | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5259147050   | SEAL, RR BUMPER, RH                    | 1.00     | \$95.50         | 25.00        | \$71.63          | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5216116010   | CLIPS PIECE, FRT & RR BUMPER           | 10.00    | \$4.80          | 25.00        | \$36.00          | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5245347010   | GUARD, RR BUMPER, LOWER                | 1.00     | \$623.50        | 25.00        | \$467.63         | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5256547900   | FILLER, RR BUMPER, RH                  | 1.00     | \$168.60        | 25.00        | \$126.45         | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 8155147281   | LENS & BODY, REAR COMBINATION LAMP, RH | 1.00     | \$489.00        | 10.00        | \$440.10         | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 8158147010   | LENS & BODY ASSY, RR BUMPER, RH        | 1.00     | \$544.40        | 10.00        | \$489.96         | Replace <i>nn</i>  | <i>X</i>    |
|             |         | 5839847050   | COVER, REAR FLOOR UNDER, RH            | 1.00     | \$189.20        | 25.00        | \$141.90         | Replace <i>nn</i>  | <i>X</i>    |

