

Section A - Accident Details

Registration Number	SHB922J
Case Reference Number	TAX/05/23/2090
Registration Date	12/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG PENG NAM
Type of Accident	Head To Side
Accident Date and Time	30/May/2023 8:50 PM
Accident Reported Date and Time	31/May/2023 12:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118560
Special Instruction to ARC, if any	HEAD TO SIDE - PLEASE CHECK RIGHT HAND PASSENGER SEAT AREA AND RIMS/TYRE AREA
Prepared Date and Time	31/May/2023 2:27 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$700.00
Total Spray Cost	\$1,574.00	\$460.00
Total Spare Part Cost	\$7,151.54	\$565.86
Total Other Cost	\$1,606.88	\$406.88
TOTAL COST	\$11,684.42	\$2,132.74
Lump Sum Total	\$11,700.00	\$2,150.00 (L/S)
Number of Repair Days	10.0	5.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / AIG
ARC / Surveyor Sign Off Date	01/06/2023 3:00 PM	01/06/2023 2:55 PM
Signature		<i>Kenneth</i>
Remarks	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2306-0105	Invoice Number	
Quotation Date	14.06.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,352.00	\$700.00
Total Labour	\$1,352.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY RIM	\$220.00	\$60.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$1,574.00	\$460.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$1,606.88	\$406.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$644.10	0.00	\$0.00	Replace	Check
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair
		6563747060	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given
		6556547010	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$37.70	0.00	\$0.00	Replace	Check
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	Replace

X }nn
X
R
X }nn
X
√ bt

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/06/2023

User ID : PohSuan

		6783633030	DOOR REAR LOCK COVER	0.00	\$10.00	0.00	\$0.00	Replace	Not Given	X	
		6905052250	DOOR LOCK REAR , RH	0.00	\$607.90	0.00	\$0.00	Replace	Not Given	X	} nn
		6787147051	WEATHERSTRIP, REAR DOOR RH	0.00	\$194.60	0.00	\$0.00	Replace	Not Given	X	
		6863047050	CHECK ASSY, REAR DOOR	1.00	\$199.40	100.00	\$0.00	Replace	Repair	R	
		6980347020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X	} nn
		8572047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X	
		6877052031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	100.00	\$0.00	Replace	Repair	R	
		6875020122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	100.00	\$0.00	Replace	Repair	R	
		6700347210	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R	
		7585047910	MOULDING ASSY, BODY ROCKER PANEL , RH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given	X	
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X	} nn
		8158147010	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X	
		8155147281	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X	
		5256547900	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X	} nn
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$623.50	0.00	\$0.00	Replace	Not Given	X	
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X	
		5259147050	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	X	
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X	} nn
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given	X	
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X	
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X	} nn
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X	
		5215947913	COVER, RR BUMPER ASSY	0.00	\$478.90	0.00	\$0.00	Replace	Not Given	X	
Total					\$11,159.44		\$707.33				

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	707.33	
	-20%	
	565.86	
+	700.00	L/S \$2,150/-
+	866.88	
	2,132.74	