

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	INCOME INSURAN	NCE LTD	Re	f:	CS3/INC23005567/Rny3m4	
	75 BRAS BASAH FINCOME CENTRE	Da	ite:	14/06/2023		
	ATTN: RAJESWAR	RY	Co	de:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKL 6900U	Veh. Inspected		SKR 1733L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1225472-002	Excess (\$)		0.00	
	Assign From	ANNA YEO	Assign Date		31/05/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	AUDI A3 SEDAN 1.4 TFSI AMB	c.c		1395	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	WAUZZZ8V9F1070582	Colour		WHITE	
	Odometer	122183 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	TRIANGLE		6 mm	
	L/H Front Tyre	225/45 R17	TRIANGLE		6 mm	
	R/H Rear Tyre	225/45 R17	TRIANGLE		6 mm	
	L/H Rear Tyre	225/45 R17	TRIANGLE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
5.	5. General Information					
	Accident Date	30/05/2023	Inspect Date / Tim	ie	06/06/2023 (12:26 PM)	
	Survey held at	V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/INC23005567/Rny3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser