

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/GRB23005572/TQY3M4**Date:** 09/06/2023**REFERENCE**

|                              |                                       |                             |                  |
|------------------------------|---------------------------------------|-----------------------------|------------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D21MFL0000447_02 |
| <b>Claimant Vehicle No :</b> | SJP5385D                              | <b>Insured Vehicle No :</b> | SLP4338Z         |
| Date of Loss:                | 29/05/2023                            | Nature of Claim:            | TP               |
|                              |                                       | Claim No:                   | N/A              |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJP5385D</b>                   | Engine No:  | 0                 |
| Make & Model:               | SUZUKI SWIFT, 1.5 (A)             | Chassis No: | JSAEZC21S00550854 |
| Reg. Date:                  | 01/03/2009 (Man. Year: 2009)      | Odometer:   | 161811 km         |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1490 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/60R15     | Rear Tyre Size:  | 185/60R15     |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                     | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items       | 0.00              | 0.00              | 0.00              |               |
| Labour                    | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour          | 0.00              | 0.00              | 0.00              |               |
| Towing                    | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (\$\$)</b> | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |

**INSPECTION**

|                             |            |               |                                                                                           |
|-----------------------------|------------|---------------|-------------------------------------------------------------------------------------------|
| Date of Assignment:         | 01/06/2023 |               |                                                                                           |
| Date Inspected:             | 01/06/2023 | Inspected At: | HORIZON AUTO TUNERS<br>25 KAKI BUKIT ROAD 4,<br>#01-48, SYNERGY @ KB,<br>SINGAPORE 417800 |
| Estimated Period of Repair: | 0.0 days   |               |                                                                                           |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



REPAIR DETAILS

|               |                                                                                                                                                                              |                                                        |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                        |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 07 Jun 2023)          |
| Parts:        | 144                                                                                                                                                                          | SUZUKI SWIFT 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| Print Code:   | (Unsubmitted, no print-code for SJP5385D)                                                                                                                                    |                                                        |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

Recommended Parts

There are no new parts selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >