

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06839

Vehicle Insured : SMN4523D  
Accident Date : 17-May-2023

Date : 22-May-2023

Our Ref : 023112 (CHINA) / CHAN

PAGE : 1

ANG TECK KEE (HONG ZE QI)  
24A CONWAY GROVE  
Singapore 558241

*Not Notified  
11 May &  
Previous After Rain 5 days*

ESTIMATED COST OF REPAIR FOR MIT.ATTRAGE 1.2 CVT SLQ9404C

1 pc Rear n/s fender  
1 pc Rear w/s glass moulding  
1 pc Rear bumper fascia  
1 pc N/s Taillamp  
1 pc Rear n/s bumper side retainer

*B/Bn* 723.00 —  
*na* 78.00 —  
*Bn* 708.00 —  
*na* 276.00 X  
*na* 26.00 —

1,811.00

Less 10% : 181.10

*na* 1,629.90  
*4dm* 60.00 sn

1 pc Rear w/s glass sealant

To remove & refix rear windscreen  
glass and conduct water leak test.

150.00 *1201*

To remove roof lining, front and  
rear seats, trim board and carpet

120.00 *1001*

To apply undersealing

60.00 *301*

To putty and spray replaced parts

600.00 *4401*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

700.00 *6001*

Total : S\$ 3,319.90

Singapore Dollars Three Thousand Three Hundred  
and Nineteen and Cents Ninety

**Only** Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: