



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO23005577/Unp3q2 Date: 16/06/2023 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SLX 839D	<b>Veh. Inspected</b>	SLE 293C
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2302215/THE	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	01/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	LAND ROVER DISCOVERY SPORT (A)	<b>c.c</b>	1999
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	SALCA2AG0GH613760	<b>Colour</b>	WHITE
<b>Odometer</b>	128035 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	235/60 R18	PIRELLI	6 mm
<b>L/H Front Tyre</b>	235/60 R18	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	235/60 R18	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	235/60 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
<b>Accident Date</b>	28/05/2023	<b>Inspection Date</b>	05/06/2023
<b>Survey held at</b>	Auto Bay@ Kaki Bukit Avenue 6 Entrance 'A' #01-04		
<b>Repairer</b>	KT GARAGE PTE LTD		
<b>5a. Remarks</b>			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>