



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref: CS3/UOI23005583/y3	
146 ROBINSON ROAD		Date: 01/06/2023	
#02-01 UOI BUILDINGSINGAPORE 068909		Code: UOI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SBD 18E	Veh. Inspected	SMR 451H
Policy No.		Coverage (\$)	0.00
Claim No.	M12D00142306	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	01/06/2023
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/06/2023	Inspection Date	06/06/2023
Survey held at	60 Jalan Lam Huat #07-35/36 Carros		
Repairer	WELLTAC AUTO SPRAY CENTRE		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			