

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 7623G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT Q5 EMBLEM	NOT NECESSARY	100.00	-
1	REAR BOOT 2.0T EMBLEM	NOT NECESSARY	100.00	-
1	REAR BOOT QUATTRO EMBLEM	NOT NECESSARY	100.00	-
1	REAR BOOT AUDI LOGO	NOT NECESSARY	145.00	-
1	REAR BOOT LOCK TOP	NOT NECESSARY	180.00	-
1	REAR BOOT LOCK LOWER CATCH	NOT NECESSARY	155.00	-
1	REAR BUMPER	DENTED/ DEFORMED	1,657.00	1,657.00
2	REAR BUMPER SIDE RETAINER L&R @\$88.00	CRACKED	176.00	176.00
2	REAR BUMPER TOWING HOOK COVER L&R @\$48.00	TWISTED	96.00	96.00
1	REAR BUMPER ENFORCEMENT	BENT	636.00	636.00
2	REAR BUMPER REFLECTOR LAMP L & R @\$315.00	CRACKED	630.00	630.00
2	REAR BUMPER PARKING SENSOR @\$252.00	MALFUNCTION	504.00	504.00
1	REAR BOOT RUBBER	NOT NECESSARY	204.00	-
	LESS 5% DISCOUNT		-234.15	-184.95
			4,448.85	3,514.05
	<u>LABOUR</u>			
	REMOVE & INSTALL REAR BOOT CARPET.	NOT NECESSARY	120.00	-
	REMOVE AND INSTALL REAR BUMPER, REAR LAMP. KNOCKING REAR BOOT, REAR END PANEL, SPARE TYRE PANEL & RESTRAIGHTEN BODY.		1,500.00	600.00
	SPRAY PAINTING.		1,100.00	600.00
	CHECK WIRING SYSTEM.		25.00	25.00
	RESET & RENEW PARKING SENSOR.		80.00	50.00
			2,825.00	1,275.00
	GRAND TOTAL		7,273.85	4,789.05



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI23005584/Uny3m4

MARKET VALUE: \$85,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$25,551.00=NETT VALUE: \$59,449.00

CHUA KANG SENG

Licensed Appraiser