

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AM ENGINEERING & CONSULTANCY PTE. LTD.
 1002 TOA PAYOH INDUSTRIAL PARK

#03-1433

Singapore 319074

TEL: 82731521

ATTN:

Estimate No: MC1903532

Date: 31 May 2023

Policy No: D23MTPCVE000709

Veh Reg No: GBE8135S

Make/Model: NISSAN CABSTAR 3.0

5M/T ABS 2DR 2WD

EURO 5

Your Ref No: GBE8135S

Claim Type: Third Party → Alliance

Accident Date: 29/05/2023

TP Veh Reg No: YP7517A

LCC

1080.
6/6/23

Not Authorized
1/1/23

Meany After Part

5 days

Estimate Repair Cost to Vehicle No : GBE8135S

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 FRONT WINDSCREEN MOULDING TOP LH & RH	2 PC	236.00	—
2 FRONT WINDSCREEN MOULDING SIDE LH & RH	2 PC	180.00	—
3 FRONT WINDSCREEN MOULDING BTM	1 PC	38.00	—
4 WIPER PANEL	1 PC	588.00	—
5 WIPER PANEL MLDG	1 PC	33.00	—
6 FRONT PANEL	1 PC	1,580.90	✓
7 FRONT PANEL CABSTAR LOGO	1 PC	45.00	—
8 RADIATOR GRILLE	1 PC	670.00	X
9 RADIATOR GRILLE EMBLEM	1 PC	97.00	X
10 RADIATOR GRILLE BKT	1 PC	39.00	X
11 HEADLAMP LH & RH	2 PC	1,176.00	X
12 HEADLAMP LOWER COVER LH & RH	2 PC	236.00	X
13 HEADLAMP LOWER COVER CLIPS	2 PC	13.00	X
14 FRONT BUMPER	1 PC	1,155.00	X
15 A/C HEATER	1 PC	1,513.00	X
16 A/C BLOWER	1 PC	645.00	X
17 SIDE MIRROR LH	1 PC	201.00	X
18 SIDE MIRROR STAY LH	1 PC	248.00	X
19 UNDER MIRROR	1 PC	72.00	X
		8,765.90	
	Less 30%	2,629.77	6,136.13
Special Nett			
20 INNER SEAL	1 PC	20.00	—
21 WINDSCREEN SEALANT	1 PC	40.00	—
22 NUMBER PLATE	1 PC	35.00	X
23 RADIATOR COOLANT	1 PC	30.00	X
		125.00	125.00
LABOUR			
24 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	152
25 TO REMOVE & REPLACE A/C HEATER & BLOWER	1 PC	180.00	X
26 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
27 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	350.00	2501

Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AM ENGINEERING & CONSULTANCY PTE. LTD.
1002 TOA PAYOH INDUSTRIAL PARK
#03-1433
Singapore 319074
TEL: 82731521
ATTN:

SURVEYOR COPY

Estimate No: MC1903532
Date: 31 May 2023
Policy No: D23MTPCVE000709
Veh Reg No: GBE8135S
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

Your Ref No: GBE8135S
Claim Type: Third Party
Accident Date: 29/05/2023
TP Veh Reg No: YP7517A

Estimate Repair Cost to Vehicle No :GBE8135S

Description	Quantity	List Price	Amount
		S\$	S\$
28 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	401
29 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	301
30 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT PANEL,UPPER PANEL.TO KNOCK & REPAIR FRONT FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	600
31 TO SPRAY WIPER PANEL,FRONT PANEL,FRONT FENDER LH.	1 PC	700.00	400
		2,310.00	2,310.00
		Total	S\$ 8,571.13
		Add GST @ 8%	685.69
		Total Amount Payable	S\$ 9,256.82

TOTAL: SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED FIFTY SIX AND CENTS EIGHTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Zila
Ah Lim Motor Company

AUTHORISED SIGNATURE