

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Zheng Hanyang

Date: 06 Jun 2023

**Preliminary Advice**

Vehicle No	: YQ7631Y	Accident Date	: 31/05/2023
Make	: TOYOTA DYNA 1.5T	Policy No.	: DMCG22010753
Assignment Date	: 01/06/2023	Excess	: S\$500.00
Date of Inspection	: 05/06/2023	Est. Duration of Repair	: 9
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29 SINGAPORE 533758		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,880.70
Revised Amount	:S\$	4,220.60
Check Items (Estimated)	:S\$	4,871.10
Total	:S\$	9,091.70
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	42,838.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,162.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.