

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala

Date: 04 Jul 2023

Preliminary Advice

Vehicle No	: SML682P	Accident Date	: 22/03/2023
Make	: LEXUS ES250	Policy No.	: 1002003297
Assignment Date	: 05/06/2023	Excess	: S\$1,000.00
Date of Inspection	:	Est. Duration of Repair	:
Inspection At	:		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	92,463.47
Revised Amount	:S\$	68,367.61
Check Items (Estimated)	:S\$	21,901.44
Total	:S\$	90,269.05
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	64,331.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,669.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis. Kindly advise the repair cost offer to workshop.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.