

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Vimmala

Date: 06 Jun 2023

**Preliminary Advice**

Vehicle No	: SML682P	Accident Date	: 22/03/2023
Make	: LEXUS ES250	Policy No.	: 1002003297
Assignment Date	: 05/06/2023	Excess	: S\$1,000.00
Date of Inspection	: 05/06/2023	Est. Duration of Repair	: 30
Inspection At	: BORNEO MOTORS		

**Point of Impact / General Description of Damages**

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	92,463.47
Revised Amount	:S\$	68,367.61
Check Items (Estimated)	:S\$	21,901.44
Total	:S\$	90,269.05
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	64,331.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,669.00

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( ) Lump Sum repair
  
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
PENDING FOR INVESTIGATION.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.