

(08/11/13) Wef

ASS. REC. BY: ASRM

REF:

CS/LPC 23005616/Rny3

956c

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: YQ 2681Kat Workshop m/s Woon Mengof BUKIT BATUKInsured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

11amRemark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 142K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YQ 2681K Yr Regn: 2020 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer orMake: SCANIA P250B4X2N2 c.c 6690Colour: BLUG A/C: Insured / Std / NI / NASp.Reading: 49674 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 452P4X20005513744Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NH / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5R: 5/D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 11/05/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 124K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

28, Gul Drive, Singapore 629476 Tel : 63531131

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

To : Lonpac Insurance Bhd
Motor Claims Dept

OD CLAIM

Date : 01 Jun 2023

Dear Sirs :

Fax : 6896 8706

RE : ESTIMATE COST FOR SCANIA P250 - YQ2681K
ALONG 17 WOODLANDS DRIVE 17 ON 11/05/2023

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Trim panel lh ?	1pc	\$ 139.00
4	Front headlamp seal lh <i>su</i>	1pc	\$ 34.88
5	Front headlamp end cover <i>de</i>	1pc	\$ 30.00
6	Front headlamp bracket lh ?	1pc	\$ 68.00
7	Front headlamp lh <i>bu</i>	1pc	\$ 1,314.75
8	Front headlamp hinge pin lh ?	1pc	\$ 35.00
10	Front headlamp beam lh ?	1pc	\$ 247.25
11	Front headlamp bush lh ?	1pc	\$ 16.50
12	Wheel arch trim panel top lh <i>su</i>	1pc	\$ 330.00
13	Wheel arch trim panel front lh <i>su</i>	1pc	\$ 280.00
14	Wheel arch trim panel lh <i>bu</i>	1pc	\$ 275.00
15	Wheel LED lh ?	1pc	\$ 195.25
16	Wheel trim lh <i>bu</i>	1pc	\$ 213.62
17	Front step panel lh <i>su</i>	1pc	\$ 1,281.00
18	Boarding step unit lh <i>su bu</i>	1pc	\$ 1,150.25
19	Step plate upper <i>su</i>	1pc	\$ 470.00
20	Step plate lower <i>su</i>	1pc	\$ 468.87
21	Front bumper side cover <i>de my</i>	1pc	\$ 89.00
22	Front bumper cover lh <i>su</i>	1pc	\$ 789.12
Sum Carried Forward			\$ 7,427.49

Sum Carried Forward**\$ 7,427.49**

23	Front door side mirror lh (complete) <i>bro ✓</i>	1pc	\$	1,440.60
24	Front door mirror top lh <i>bro ✓</i>	1pc	\$	365.75
25	Front door lh <i>lf ✓</i>	1pc	\$	4,800.00
26	Rear mudguard lh (front) <i>son ✓</i>	1pc	\$	456.00
27	Rear mudguard lh (rear) <i>son ✓</i>	1pc	\$	815.00
28	Rear taillamp lh ?	1pc	\$	592.00
				\$ 15,896.84
				\$ 2,384.53
				\$ 18,281.37

Add 15%

Labour Charge & Misc

To remove, repair, replace & install front damaged parts.	}	\$	1,800.00 <i>1200</i>
To R & R wiring	}	\$	150.00 <i>60</i>
To R & R refrigerated box <i>putty?</i>		\$	800.00 <i>500</i>
To putty & spray painting.		\$	1,200.00 <i>600</i>
Total		\$	<u>22,231.37</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

All prices quoted are subjected to GST.

This is a computer generated document. No signature is required.

Rashu
Hp 90010068
6 days
P/P
06/06/23 @ 1100
EXCESS TBA
Revert
Resy before
putty

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	956C
Vehicle No.:	YQ2681K
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2023
Vehicle Make:	SCANIA
Vehicle Model:	P250B4X2NZ
Primary Colour:	Multicolor
Manufacturing Year:	2018
Engine No.:	DC0711222312087
Chassis No.:	YS2P4X20005513744
Maximum Power Output:	-
Open Market Value:	\$86,881.00
Original Registration Date:	24 Aug 2020
First Registration Date:	24 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$4,345.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	23 Aug 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$24,100.00
COE Rebate Amount:	\$17,375.00
Total Rebate Amount:	\$17,375.00

The information contained herein is correct as at 07 Jun 2023

OK