



Immediate Advice

To : HSBC Life (Singapore) Pte. Ltd.

Date: 05/07/2023

Survey Details:

Date of loss	31-May-23
Date of appointment	5-Jun-23
Date of survey	5-Jun-23
Location of survey	THIAM HENG HUAT PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKZ336P
Make and Model	MERCEDES C 180(1595cc)
Date of registration	6/1/2016
Excess	
Market Value/ Book Value	\$ 71,000.00 (est)
Parf/COE Rebate	\$ 37,777.00 (est)
Nett Value/ ERV	\$ 33,223.00 (est)

Repair details:

Initial Estimate	\$ 20,506.21
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 8,740.98
Check items (estimate)	NIL
Labour	\$ 1,220.00
Supplementary	NIL
Total	\$ 9,960.98
Lump Sum(if applicable)	\$ 7,800.00

Number of days for repair	<u>5</u>
---------------------------	----------



Remarks:

OID CHANGED LANE.

Mandate:

Liability(TP)	100%	
Proposed repair cost (+8%GST)	\$ 8,424.00	\$ 8,424.00
Loss of use (7DAYS X \$60.00)	\$ 420.00	NIL
Loss of rental(7DAYS X \$100)(w/GST)	NIL	\$ 756.00
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 26.75	\$ 26.75
Others	NIL	NIL
Proposed Total	\$ 8,870.75	\$ 9,206.75

* 18 REPAIR DAYS + 3SUNDAY + 1PH(01/05/23) + 1PRS =23DAYS