

ASS. REC. BY: Taufik

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1225824-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SM9132B Yr Regn: 20.9, oct.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai winia c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 566927 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH/C851/C614/186512Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NP / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: ---

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 01/06/23Survey held at Comfort LodgeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufik confirmed lump sum \$3350 and 3 days
	(red. \$2024.44, 38%)

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 3

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH9132B
MAKE HYUNDAI
MODEL IONIQ

DATE: 01.06.23
MVA JUMANI
DOA: 01.06.23

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING			\$55.80
1	REAR BUMPER BEAM			\$394.80
1	REAR BUMPER TOW COVER			\$98.80
	FRT BUMPER ASSY			\$481.10
	FRT BUMPER CENTRE MOULDING			\$368.50
	FRT FOG LAMP GRILLE LH			\$93.45
1	RADIATOR GRILLE			\$1,568.60
	rear bumper stay bt ✓		\$138.10	
	SUB TOTAL		3680.55	
	LESS 20%		2944.44	
	DISCOUNTED TOTAL			\$3,542.45
				\$708.49
				\$2,833.96
	REAR BUMPER MAT		180	need ✓ x \$50.00
	REVERSE SENSOR		10%-162	✓ \$180.00
	SUB TOTAL NET		50	
			212	\$230.00
	Labour Charge			
	PANEL BEATING			525 \$1,400.00
	SPRAY PAINT			500 \$700.00
	REMOVE/REFIX REVERSE SENOR			30 \$50.00
	CHECK WIRING		1055	nn x \$50.00
	TOTAL LABOUR		4211.44	\$2,200.00
	ESTIMATE TOTAL		1/s\$3350 3 days	\$5,263.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged parts during resurvey

- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Tan Joon 97495749
Wp, 1/6/23 430pm
1/s Ronny after repair
Tan Joon C 1/6/23 430pm
3 days

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 01.06.2023 16:09

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5898956

JC NO305556502

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


DUNT CARD NO.

REGN NO.: SH 9132B	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 01.06.2023 14:05
YR OF MANU. 22.10.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU186512	COMPLETION DATE/TIME:

Accident Date: 01.06.2023
ATURE: 3P.01.06.23

JOB DESCRIPTION

'NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

: SH 9132B

JU INCOME

Vehicle No.:

SH 9132B

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard