

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS23005621/UNY3E2**Date:** 08/06/2023REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
<b>Claimant Vehicle No :</b>	FBC9234T	<b>Insured Vehicle No :</b>	SKW8221A
Date of Loss:	13/05/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBC9234T</b>	Engine No:	G372EE002475
Make & Model:	YAMAHA FZ150I, 150cc	Chassis No:	PMYKG025080002475
Reg. Date:	20/08/2008 (Man. Year: 2008)	Odometer:	77849 km
Colour:	Green		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	110-80-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	01/06/2023	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	05/06/2023 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	0.0 days	Singapore 533758

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$5,000.00
OMV :	\$2,390.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$5,005.00
COE Rebate (2) :	\$2,245.00
Total Rebate (1) + (2) = :	\$2,245.00

The total amount incurred will be Market Value \$5,000.00 minus Total Rebate \$2,245.00 = \$2,755.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Jun 2023)	
Parts:	N/A	YAMAHA FZ150I 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC9234T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >