



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

ECICS LIMITED
T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBC9234T
MAKE/MODEL : YAM / FZ150

NO. : 43657

DATE : 31/05/2023
CLAIM NO. : 12192
POLICY NO. : PNMC2323-00000440
FROM : RAYMOND

*Not Authorized
here
5/6/23
maybe TOTAL LOSS?*

(Page 1 of 7)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY / FRAME P/N: 29844 - (REPORTED BY MECHANIC)	Repair	1.00	\$550.00	550.00
2	AXLE SWING ARM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	54.00
3	BALANCER HANDLE P/N: 36390 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	29.00
4	BAR HANDLE P/N: 39103 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$102.00	102.00
5	BEARING ARM BUSH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
6	BEARING STEERING CONE UPPER P/N: 36392 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
7	BOLT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
8	BOLT, WITH WASHER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
9	BRACKET BOX REAR (HLD) P/N: 53994 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$138.00	138.00

*43657 *

bizSAFE



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	BRACKET FOOTREST - (REPORTED BY MECHANIC)	REPLACE	1.00	\$141.00	141.00
11	BRACKET FOOTREST FRONT RH P/N: 36393 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$99.00	99.00
12	BUSH SWING ARM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
13	CABLE CLUTCH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
14	CAP TANK RECOVERY COOLANT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.00	4.00
15	CLAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
16	CLIP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
17	COLLAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
18	COLLAR FUEL TANK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
19	COOLANT (MOBIL) ANTIFREEZE P/N: 60213 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
20	COVER CHAIN CASE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00
21	COVER CHAIN CASE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
22	COVER CRANKCASE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$114.00	114.00
23	COVER SAP SWING ARM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
24	COVER SCOOP, AIR 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00

*43657 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
25	COVER SCOOP, AIR 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
26	COVER SIDE 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	15.00
27	COVER SIDE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
28	COVER SIDE 3 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$76.00	76.00
29	COVER SIDE 5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
30	COVER SIDE REAR RH P/N: 36395 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00
31	COVER WATER PUMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00
32	COVER, OUTER 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
33	COVER, OUTER 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
34	COVER,BALL RACE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	53.00
35	CROWN, HANDLE P/N: 54943 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00
36	ELBOW - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
37	EMBLEM - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50	9.00
38	EXHAUST ASSY P/N: 54933 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$497.00	497.00
39	FOOTREST FRONT LH P/N: 39116 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00

*43657 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
40	FOOTREST FRONT RH P/N: 36396 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
41	FORK SET ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$860.00	860.00
42	FUEL TANKS ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$246.00	246.00
43	GASKET P/N: 56836 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$52.00	52.00
44	GASKET EXHAUST PIPE P/N: 56840 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
45	GRIP HANDLE LH P/N: 39104 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
46	GRIP HANDLE RH P/N: 75252 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
47	GRIP HANDLE SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.00	4.00
48	GROMMET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
49	GUARD CHAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
50	HEADLAMP ASSY P/N: 75258 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$81.00	81.00
51	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$86.00	1,376.00
52	MASTER CYLINDER PUMP FRONT ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$100.00	100.00
53	METER ASSY P/N: 54939 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$465.00	465.00
54	MID GROMMET P/N: 21154 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00

*43657 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
55	MUDGUARD FRONT (RED) P/N: 36401 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	68.00
56	NUT FLANGE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
57	OIL ENGINE (MOBIL) ADVANCE RACING 1 10/40 P/N: 72811 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	29.00
58	PEDAL BRAKE P/N: 36402 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$64.00	64.00
59	PEDAL GEAR P/N: 39110 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00
60	PROTECTOR MUFFLER (REAR) P/N: 36403 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$141.00	141.00
61	PROTECTOR MUFFLER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
62	RACE BALL (UPPER) P/N: 26748 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
63	RACE BALL UPPER 2 P/N: 26830 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	15.00
64	REPAIR BODY FRAME P/N: 16947 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$120.00	120.00
65	RETAINER BALL BEARING P/N: 36406 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
66	RUBBER FOOTREST FRONT P/N: 36394 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
67	SCREW P/N: 54938 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	3.00
68	SCREW TAPPING P/N: 45274 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
69	SCREW, FLAT HEAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50

*43657 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
70	SIGNAL FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00
71	SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00
72	SPRING REAR PEDAL BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
73	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
74	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
75	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2.50	2.50
76	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2.50	2.50
77	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
78	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
79	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
80	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
81	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
82	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	39.00
83	STICKER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	39.00
84	STOPPER MAINSTAND P/N: 54930 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00

*43657 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
85	SWING ARM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00
86	TANK RECOVERY COOLANT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
87	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$65.00	65.00
88	TUBE HAND GRIP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.58	1.58

SUB TOTAL

\$6,912.58

GST @ 8 %

\$553.01

GRAND TOTAL (SGD)

\$7,465.59**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*43657 *

bizSAFE₃