



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI23005637/Any3m4 Date: 23/06/2023 Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBB 8276J	Veh. Inspected	SKA 3392M
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D00052306	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	04/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	MR053REE104112175	Colour	SILVER
	Odometer	103969 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65R15	MICHELIN	6 mm
	L/H Front Tyre	195/65R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65R15	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/05/2023	Inspection Date	05/06/2023
	Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	