

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

Singapore

Jumani
CTPL
LLK

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/06/2023
Vehicle Reg. No.:	SHB4140Y	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	06/08/2019
Vehicle Colour:	BLUE		
Engine No:	G4LEKU298705	Chassis No:	KMHC851CVKU164897
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,753.48
Miscellaneous Items	11.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,114.48
+ GST 8.00% (S\$)	249.16
Nett Amount (S\$)	3,363.64

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 05 Jun 2023)

Parts: 192

HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB4140Y/05/06/2023 10:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY ?	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CENTRE MLDG / DCF	20.00	0.00	*451.25 FL
3	1		*REAR BUMPER CENTRE BEAM ?	20.00	0.00	*394.80 FL
4	10		*REAR BUMPER CENTRE CLIPS ?	20.00	0.00	*22.00 FL
5	1		*BOOTLID EMBLEM - IONIQ XNW	20.00	0.00	*31.30 FL
6	1		*BOOTLID EMBLEM - HYBRID XNW	20.00	0.00	*24.30 FL
7	1		*BOOTLID EMBLEM - H XNW	20.00	0.00	*28.00 FL
8	1		*REAR BUMPER SIDE BRACKET RH ?	20.00	0.00	*55.80 FL
9	1		*REVERSE SENSOR XSVL	0.00	0.00	*180.00 F
10	1		*REAR BOOT COMFORT LOGO / NGL	0.00	0.00	*30.00 F
11	1		*REAR BOOT COMFORT TEL.NOS LOGO / NGL	0.00	0.00	*30.00 F
12	1		*REAR BOOT APPS LOGO / NGL	0.00	0.00	*40.00 F
13	1		*ADVERTISEMENT LOGO - BOOTLID X / NGL	0.00	0.00	*100.00 F
14	2		*ADVERTISEMENT LOGO - FENDER / NGL	0.00	0.00	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,046.85
- List Item Discount on L Items (\$\$)	293.37
Total Parts (\$\$)	1,753.48

ComfortDelGro Engineering Pte Ltd/SHB4140Y/05/06/2023 10:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

NAZ LEX
5/6/2023 1645
L/S
20 May
(CHECK ITEM PHOTO)
ATTACH REPAIR PHOTO

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	320 700.00
2	SPRAY PAINT	New	230 600.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
Gross Labour Cost (S\$)			1,350.00

ComfortDelGro Engineering Pte Ltd/SHB4140Y/05/06/2023 10:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: