

(08/11/13) wef

ASS. REC. BY: John

REF:

CS/FCI 23005645/RAG3

417K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 1334Rat Workshop m/s TDWTR TRANSITof MANTRA R7Insured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SMB 1334R Yr Regn: 2013 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN NL320F (A22) c.c. 105/8Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: 047903 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA 22ZZ807001778Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 275/70R22-5R: 8/0

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 26/05/23 D.O.I. 06/06/23Survey held at TDWTR TRANSIT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	16:29HRS
ACCIDENT DATE	26-May-23
BUS CAPTAIN NAME	JIVARATHNAM A/L CHUMARAN
THIRD PARTY CLAIM AGAINST	MSFCIL - GO AHEAD SPORE

BUS REGISTRATION NUMBER	SMB1334R
BUS TYPE (SD/DD)	SD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	REAR LAMP STOP ASSY LED (RED) <i>CM</i>	2	\$ 616.00
2	OS REAR SIGNAL LAMP <i>CM</i>	1	\$ 413.60
		8% GST	\$ 82.37
		PARTS TOTAL COST	\$ 1,111.97

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • ITEM NOS 1 - 2	\$ 1,300.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- • OS REAR LAMP COVER • OS REAR DOME	\$ 1,950.00
SPRAY PAINTING :- • OS REAR LAMP COVER • OS REAR DOME	\$ 1,280.00
8% GST	\$ 362.40
LABOUR TOTAL COST	\$ 4,892.40

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

BUS TYPE (SD / DD) SD

LOSS OF USE COST

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

Rasul
Hp 9011568
3 days
06/06/23 P1430

DATE IN	26-May-2023
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	5
	\$1,500.00

Resy after repair

SUMMARY	
SECTION NO.	COST
1	\$ 1,111.97
2	\$ 4,892.40
3	\$ 1,500.00
TOTAL	\$ 7,504.37