

Your Ref : SNM23D203836/C02/TANCHC

Date: 14<sup>th</sup> June 2023

Our Ref : CS/CTI23005649/Uvp3e2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE JUD 1938****INSURED VEHICLE: SJN 6938M****ACCIDENT ON 23/05/2023**

Instruction was received to inspect the vehicle Reg. No. JUD 1938. The inspection was conducted on 05/06/2023 at the premises of M/s Erofia Motor Trading Pte Ltd, 1 Kaki Bukit Avenue 6 #02-62, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: JUD 1938
Make/Model	: Yamaha 135LC
Year of Registration	: 2020
Body Colour	: Blue
Chassis Number	: PMYUG0810L0193951
Engine Capacity	: 134 cc

The vehicle sustained damages at the front portion and o/s body. The Estimated repair cost of such vehicle is S\$5,872.60 (Sin Dollars: Five Thousand Eight Hundred Seventy-Two and Sixty cents only.) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value S\$ 1,700.00 (est) (RM5,700.00÷3.3)

Less: Salvage Value (S\$ 100.00)

Nett Liability S\$ 1,600.00

S\$ 1,600.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 5,872.60

Nett Liability

S\$ 5,872.60

(a) – (b) =

(S\$ 4,272.60)

The amount of estimated saving of S\$4,272.60 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



CHUA KANG SENG

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MDATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.