

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile								
	ECICS LTD		Ī	Ref:	CS/ICS23005664/y3			
	10 EUNOS ROAD SINGAPORE POS SINGAPORE 4086	T CENTRE #09-04A	I	Date:	05/06/2023			
				Code:	ICS			
1.	Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SJW 6768P	Veh. Inspected		FH 9957S			
	Policy No.		Coverage (\$)		0.00			
	Claim No.		Excess (\$)		0.00			
	Assign From	AFIQ KAMAL	Assign Date		05/06/2023			
2. Vehicle Particulars & Condition								
	Make & Model		c.c		0			
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	-	Steering					
	Brakes		Modification					
	General							
3.	3. Conditions of Tyres							
		Size	Make		Balance			
	R/H Front Tyre				mm			
	L/H Front Tyre				mm			
	R/H Rear Tyre				mm			
	L/H Rear Tyre				mm			
4.		Description of Damages						
5.	T		Information					
	Accident Date	23/05/2023	Inspection Date	)				
	Survey held at	BAN HOCK HIN CO.PTE LTD						
		BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, SINGAPORE 533758						
5a.	Remarks							
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							

ECICS LTD Ref: CS/ICS23005664/y3

10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A

SINGAPORE 408600

Code: ICS

Date:

05/06/2023

Affiliated to Federation Internationale Des Experts En Automobile									
1.	Policy Particulars :- THIRD PARTY CLAIM								
	Insured Veh.	SJW 6768P	Veh. Inspected	FH 9957S					
	Policy No.		Coverage (\$)	0.00					
	Claim No.		Excess (\$)	0.00					
	Assign From	AFIQ KAMAL	Assign Date	05/06/2023					
2. Vehicle Particulars & Condition									
	Make & Model		c.c	0					
	Engine No.	HIDDEN	Year of Reg.						
	Chassis No.		Colour						
	Odometer	-	Steering						
	Brakes		Modification						
	General								
3.	3. Conditions of Tyres								
		Size	Make	Balance					
	R/H Front Tyre			mm					
	L/H Front Tyre			mm					
	R/H Rear Tyre			mm					
	L/H Rear Tyre			mm					
4.		Description	on of Damages						
5.			Information						
	Accident Date	23/05/2023	Inspection Date						
	Survey held at	BAN HOCK HIN CO.PTE LTD							
		BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, SINGAPORE 533758							
5a.	5a.		Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.								