



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005675/Aqy3m4 Date: 24/07/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 5100H	Veh. Inspected	GBE 5895B	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/1762	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	06/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	KDH2010182712	Colour	RED	
Odometer	147966 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	195R15C	YOKOHAMA	6 mm	
L/H Rear Tyre	195R15C	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/05/2023	Inspection Date	06/06/2023	
Survey held at	PROMPT AUTO SOLUTIONS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)REGISTRATION DATE: 22 JAN 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	