

# COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHA4349T  
 Make : HYUNDAI  
 Model : IONIQ(G2)

Date: 05/06/2023  
 Insurance: INCOME  
 MVA: MS. LOKE YY LIS

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$459.40	/CRA
10	REAR BUMPER CLIPS			\$22.00	INEL
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25	/CRA
1	REAR BUMPER REINFORCEMENT			\$394.80	?
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20	?
1	ANTENNA SMARTKEY			\$40.50	?
1	REAR BUMPER FOG LAMP			\$201.50	?
1	REAR BUMPER LOWER CTR MOULDING			\$155.00	DEF
2	REAR BUMPER SIDE BRACKET		\$55.80	\$111.60	?
	<b>SUB TOTAL</b>			\$2,112.25	
	<b>LESS 20%</b>			\$422.45	
	<b>DISCOUNTED TOTAL</b>			<b>\$1,689.80</b>	
	 REAR NUMBER PLATE WITH TRIM COVER			\$50.00	/CRA
	REAR BUMPER REVERSE SENSOR			\$180.00	XSVL
		NETT		<b>\$230.00</b>	
	<b>Labour Charge</b>				
	PANEL BEATING			\$750.00	350
	SPRAY PAINTING CHARGE			\$300.00	250
	CHECK LIGHTING/ WIRING			\$60.00	X NA
	REMOVE/REFIX REVERSE SENSOR			\$80.00	30
	<b>TOTAL LABOUR</b>			<b>\$1,190.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$3,109.80</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK  
 5/6/2023 LIS  
 2 Day  
 CHECK ITEM PHOTO  
 AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: