

Our Job Ref No : 305556567  
Date : 14.06.2023**FINALIZATION FORM**To : LKK

Fax :

Attn : NAZVehicle Reg No. : SHD7119E30.05.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: INCOME SKU7371S

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$1,550.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : NAZ LKKDate : 22/6/2023**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$26.75/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO SHD7119E  
 MAKE 10.11.2016  
 MODEL HYU- I40

30.05.2023

CHIANG/INCOME LIS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	FRONT BUMPER COVER			\$1,052.20	DEF
2	FRONT BUMPER BRACKET SIDE LH		\$24.60	\$24.60	? XSVL
1	FRONT BUMPER GRILLE LH			\$187.20	? XSVL
1	HEADLAMP LH			\$1,388.00	? XSVL
1	FRONT FENDER LH			\$663.00	XR
1	FRONT FENDER SHIELD LH			\$174.90	? XSVL
				<b>\$3,489.90</b>	
				<b>20.00%</b>	
				<b>\$697.98</b>	
				<b>\$2,791.92</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$580.00	560
	Spray Painting Charge			\$600.00	500
	Check Lighting			\$60.00	? XSVL
	Tuff Kote			\$60.00	40
				<b>\$1,300.00</b>	
				<b>\$4,091.92</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAZ LKK

5/6/2023 1620

LIS

3 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: