

OMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3801K

Make : Toyota

Model : Prius (G4A)

Date: 31/05/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$ 503.04
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER COVER			\$ 654.96
1	REAR BUMPER REINFORCEMENT			\$ 378.32
1	BACK DOOR GARNISH SUB ASSY			\$ 1,054.71
1	REAR TRUNK LID LOGO (PRIUS)			\$ 62.14
1	REAR TRUNK LID LOGO (HYBRID)			\$ 62.14
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$ 81.43
1	REAR TRUNK LID COVER			\$ 1,303.29
1	REAR WINDSCREEN GLASS WITH MOULDING			\$ 1,884.32
1	REAR BUMPER EXTENSION RH			\$ 148.10
1	REAR BUMPER TOWING COVER			\$ 82.70
1	TAIL LAMP UPPER RH			\$ 557.90
1	TAIL LAMP LOWER RH			\$ 570.00
1	REAR END PANEL GARNISH			\$ 165.80
1	REAR END PANEL			\$ 738.96
	SUB TOTAL		2441.69	\$ 8,269.81
	LESS 25%		1831.26	\$ 2,067.45
	DISCOUNTED TOTAL			\$ 6,202.36
	REAR TRUNK LID COMFORT & TEL NO. STICKER		-10%	\$ 60.00
	REAR TRUNK LID APPS STICKER		-10%	\$ 40.00
	REAR REVERSE SENSOR		235.70 -10%	\$ 135.70
			108-212.13	\$ 235.70
	Labour Charge			
	PANEL BEATING			\$ 1,100.00
	SPRAY PAINTING CHARGE			\$ 800.00
	REMOVE/ REFIX REAR WINDSCREEN GLASS			\$ 120.00
	CHECK LIGHTING		1055	\$ 60.00
	TUFF KOTE			\$ 80.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR		3098.38	\$ 2,220.00
	ESTIMATE TOTAL		45925.00	\$ 8,658.06
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

The final repair quantum will be prepared by LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items; must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphm 97495747
 'wp' 116/73 e 4pm
 L/S Resurvey after repair
 Tanphm ckhauto.com
 (2) 3 days