



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23005682/Uny3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 04/07/2023

ATTN: LIM SERENE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 764T	Veh. Inspected	FBF 9292J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1226068-001	Excess (\$)	0.00
Assign From	JULIET KOH	Assign Date	06/06/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA CBF150	c.c	149
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LALKC11A4A3461976	Colour	BLACK
Odometer	54899 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/90-18	IRC	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/90-18	IRC	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/05/2023	Inspect Date / Time	06/06/2023 (02:21 PM)
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days