

# SM AUTOMOTIVE

Block C,1 Kaki Bukit Avenue 6 Blk C #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

31/05/2023

Blk 1 Kaki Bukit Ave 6 RCB No: 53231488C GST Reg No : 53231488C

# 01-43

Singapore 417883

Accident date: 26/05/2023

TP INC

Xiao Chen.

Estimated repair cost for vehicle no: QS6806Q HYUNDAI STREX

CHASSIS: KMJWA37KMCU513103

| S/n                                                | Qty | Items                                         | U/price     | Amount             |
|----------------------------------------------------|-----|-----------------------------------------------|-------------|--------------------|
| 1                                                  | 1   | REAR BUMPER <i>Dislodged</i>                  | \$512.80    | \$512.80 ✓         |
| 2                                                  | 1   | REAR BUMPER REINFORCEMENT <i>Dented</i>       | \$347.60    | \$347.60 ✓         |
| 3                                                  | 1   | REAR BUMPER TOP GARNISH <i>New</i>            | \$66.50     | \$66.50 ✓          |
| 4                                                  | 2   | REAR BUMPER SIDE RETAINER <i>New</i>          | \$20.30     | \$40.60 ✓          |
| 5                                                  | 1   | REAR END PANEL (INNER) <i>Repair</i>          | \$270.10    | \$270.10 ✓         |
| 6                                                  | 1   | REAR END PANEL (OUTER) <i>Dented</i>          | \$586       | \$586 ✓            |
| 7                                                  | 1   | REAR END PANEL TOP GARNISH <i>cracked</i>     | \$74.20     | \$74.20 ✓          |
| 8                                                  | 1   | REAR TAILGATE <i>Dented</i>                   | \$2,620.40  | \$2,620.40 ✓ 2380. |
| 9                                                  | 1   | REAR TAILGATE LOCK <i>Key</i>                 | \$84.60     | \$84.60 ✓          |
| 10                                                 | 1   | REAR TAILGATE EMBLEM LOGO                     | \$26.20     | \$26.20 ✓          |
| 11                                                 | 1   | REAR TAILGATE EMBLEM HYUNDAI                  | \$30.20     | \$30.20 ✓          |
| 12                                                 | 1   | REAR TAILGATE EMBLEM STAREX                   | \$46.90     | \$46.90 ✓          |
| 13                                                 | 1   | REAR TAILGATE INNER TRIM BOARD <i>cracked</i> | \$297.20    | \$297.20 ✓         |
| 14                                                 | 1   | REAR TAILGATE OUTER GARNISH <i>Not a</i>      | \$41.40     | \$41.40 ✓          |
| 15                                                 | 2   | REAR TAILLAMP <i>New</i>                      | \$384.90    | \$769.80 ✓         |
| 16                                                 | 2   | REAR TAILLAMP LOWER APRON PANEL <i>Repair</i> | \$233.10    | \$466.20 ✓         |
| 17                                                 | 1   | REAR WEATHER STRIPE <i>Ext</i>                | \$136.40    | \$136.40 ✓         |
| 2 Rear Fender Inner Trim Board <i>Rit cracked.</i> |     |                                               | \$620       | 1240. 620.         |
|                                                    |     |                                               | TOTAL :     | \$6,048.90         |
|                                                    |     |                                               | LESS 20 %   | \$1,209.78         |
|                                                    |     |                                               | SUB-TOTAL : | \$4,839.12         |

4638.30  
3711.44

**SQ6806Q HYUNDAI STREX**

| S/N                          | Qty | ITEMS / SPECIAL NETT                              | U/price       | Amount                          |
|------------------------------|-----|---------------------------------------------------|---------------|---------------------------------|
| 1                            | 1   | REAR BUMPER CLIPS <i>new</i>                      | \$80.00       | \$80.00 <i>30</i>               |
| 2                            | 1   | REAR END PANEL SEALANT <i>new</i>                 | \$120.00      | \$120.00 <i>60</i>              |
| 3                            | 1   | REAR TAILGATE WINDSCREEN GLASS SEALANT <i>new</i> | \$150.00      | \$150.00 <i>60</i>              |
| 4                            | 1   | REAR NUMBER PLATE WITH CASING <i>new</i>          | \$60.00       | \$60.00 <i>+</i>                |
| 5                            | 1   | REAR REVERSE SENSOR <i>Ry d</i>                   | \$280.00      | \$280.00 <i>20</i>              |
| <i>Rees Bumper Distorted</i> |     |                                                   | <i>1200</i>   | <i>1200 850(SW)</i>             |
|                              |     |                                                   | <b>TOTAL:</b> | <b>\$690.00</b>                 |
|                              |     |                                                   | <i>1200</i>   | <b>TOTAL PARTS : \$5,529.12</b> |

**Labour charges**

|   |                                                        |                               |
|---|--------------------------------------------------------|-------------------------------|
| 1 | LABOUR FOR PANEL BEATING                               | \$1,600.00 <i>80</i>          |
| 2 | LABOUR FOR SPRAYPAINTING                               | \$1,200.00 <i>80</i>          |
| 3 | WIRING CHECK                                           | \$80.00 <i>30</i>             |
| 4 | TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS        | \$300.00 <i>60</i>            |
| 5 | LABOUR FOR REMOVE & TRANSFER REAR TWINDSCREEN GLASS    | \$150.00 <i>120</i>           |
| 6 | LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING | \$200.00 <i>60</i>            |
| 7 | <i>Labour For Remove and Transfer upholstery</i>       | <i>150 80</i>                 |
|   |                                                        | <i>Adrian Lij</i>             |
|   |                                                        | <i>L/S 06/06/23</i>           |
|   |                                                        | <b>Subtotal :- \$3,530.00</b> |
|   |                                                        | <b>Total:- \$9,059.12</b>     |

*06Days*

*total 6861.44*

*L/S: 55K*

*55K*

*06Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: