## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC8311P

Make

: HYUNDAI

Model

: IONIQ(G3)

Date: 05/06/2023

Insurance: INCOME

MVA: MS. LOKE YY ff

Qty	Parts Description / Labour		Unit Price	Amount	
1	REAR BUMPER COVER			\$	459.40
10	REAR BUMPER CLIPS			\$	22.00
1	REAR BUMPER REFLECTOR RH			\$	32.00
1	REAR BUMPER CTR MOULDING			\$	451.25
					36,
	SUB TOTAL			\$	964.65
	LESS 20%			\$	192.93
	DISCOUNTED TOTAL			\$	771.72
			NETT	\$	
	Labour Charge				
	PANEL BEATING			\$	400.00
	SPRAY PAINTING CHARGE			\$	300.00
	REMOVE/ REFIX REVERSE SENSOR			\$	60.00
	TOTAL LABOUR			\$	760.00
	ESTIMATE TOTAL			\$	1,531.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZLKK 5/6/2023 1653 2 DAM) P1P CHECK ITEM PHOTOS

BEFORE PAINT OHOTOS

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

## Acknowledged by Repairer

Signature:

Date: