

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS			
VEHICLE NO	: SMG642G	2018 NOV	TP China.
VEHICLE MODEL	: TOYOTA ALTIS		Hui Rong
CHASSIS NO	: MR053REH604585746		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Rehard</i>	1	\$ 556.40	\$ 556.40
2	REAR BUMPER SIDE HOLDER <i>Ne new</i>	2	\$ 60.40	\$ 120.80
3	REAR BUMPER REFLECTOR <i>Ne new</i>	2	\$ 59.80	\$ 119.60
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 399.50	\$ 399.50
5	REAR BUMPER REINFORCEMENT BRACKET <i>Dented</i>	2	\$ 68.20	\$ 136.40
6	REVERSE SENSOR <i>Dnd</i>	2	\$ 265.30	\$ 530.60
7	REVERSE SENSOR HOLDER <i>Ne</i>	2	\$ 25.00	\$ 50.00
8	REAR END PANEL OUTER <i>Dented</i>	1	\$ 670.10	\$ 670.10
9	REAR END PANEL TOP GARNISH <i>Dnd</i>	1	\$ 185.90	\$ 185.90
10	REAR END PANEL ANTENNA SENSOR <i>Cracked</i>	1	\$ 192.20	\$ 192.20
11	TAILLAMP <i>cracked</i>	2	\$ 394.50	\$ 789.00
12	TAILLAMP PANEL <i>Ne new</i>	2	\$ 374.90	\$ 745.80
13	TAILLAMP LOWER BRACKET <i>Cracked</i>	2	\$ 58.00	\$ 116.00
14	BOOTLID <i>Cracked</i>	1	\$ 781.10	\$ 781.10
15	BOOTLID LOCK <i>Dnd</i>	1	\$ 399.50	\$ 399.50
16	BOOTLID WEATHERSTRIPE <i>At</i>	1	\$ 175.80	\$ 175.80
17	BOOTLID HINGE <i>Ne new</i>	2	\$ 79.60	\$ 159.20
18	BOOTLID REFLECTOR <i>Ne new</i>	2	\$ 379.80	\$ 759.60
19	TOYOTA LOGO <i>?</i>	1	\$ 58.90	\$ 58.90
20	COROLLA WORDING <i>?</i>	1	\$ 39.30	\$ 39.30
21	ALTIS WORDING <i>?</i>	1	\$ 43.60	\$ 43.60
22	REAR FENDER INNER TRIM BOARD <i>Ne new</i>	2	\$ 338.00	\$ 676.00
23	SPARE TYRE PANEL <i>Repas</i>	1	\$ 974.50	\$ 974.50
24	SPARE TYRE PANEL TOP BOARD <i>Ne new</i>	1	\$ 292.10	\$ 292.10
25	SPARE TYRE PANEL LOCK SCREW <i>?</i>	1	\$ 33.40	\$ 33.40
26	REAR EXHAUST PIPE <i>?</i>	1	\$ 781.10	\$ 781.10
27	REAR EXHAUST PIPE MOUNTING <i>Ne</i>	1	\$ 35.90	\$ 35.90
28	REAR EXHAUST PIPE GASKET <i>Ne</i>	1	\$ 34.20	\$ 34.20
29	REAR EXHAUST HEAT SHIELD <i>?</i>	1	\$ 145.80	\$ 145.80

5124.30
3843.22

TOTAL PRICE: \$ 10,002.30
LESS 25% \$ 2,500.57
SUB TOTAL PRICE: \$ 7,501.73

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>?</i>	1	\$ 30.00	\$ 30.00
2	REAR BUMPER PLATE HOLDER <i>Ne</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>Nec.</i>	1 SET	\$ 30.00	\$ 30.00

4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
5	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00
7	REAR FENDER INNER TRIM CLIPS <i>gap</i>	2 SET	\$ 30.00	\$ 60.00
8	SPARE TYRE PANEL SEALANT <i>gap</i>	1 SET	\$ 60.00	\$ 60.00
			TOTAL :	\$ 770.00

110

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>800</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>60</i>	
5	TO REMOVE UPHOLSTRY & REAR SEAT	\$ 280.00	<i>60</i>	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
7	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
8	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	<i>60</i>	
9	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>X</i>	

TOTAL: \$ 3,830.00

1910.

ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,271.73
 TOTAL LABOUR COST: \$ 3,830.00
 TOTAL REPAIR COST: \$ 12,101.73

Total: 5863.22
4/5: 4.7K -
06 Days.

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: