



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	06/06/2023 11:19 (SGT)
Reported by	Actual Driver
Date of Accident	05/06/2023 07:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TWDS CHANGI (AFTER EUNOS EXIT)
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SJH5939Z

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	BOO CHOR POH
NRIC No	SXXXX178C
Email Address	shermen@agvaselections.com
Mobile Phone No	(Phone) +65-98430959
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1900015593-04

#### DRIVER

Name of Driver	TAN SIEW WEE (CHEN XIUWEI)
NRIC No	SXXXX374Z
Date Of Birth	21/06/1982
Occupation	Indoor

Date Of Driving Pass .....	26/01/2010
Driving experience .....	13 YEARS AND 5 MONTHS
Gender .....	Female
Mobile Number .....	(Phone) +65-98430959
Alt. Phone Number .....	-
Email Address .....	NO@EMAIL.COM
Address .....	BLK 147 LOR 2 TOA PAYOH #18-346
Address complement .....	-
Postcode .....	310147
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Spouse
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Head to Rear
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SMU5279R
Vehicle Manufacturer .....	Kia
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Private car
Name of Driver .....	-
Contact Number .....	(Phone) +65-86129954

Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time: [Signature] 06/06/2023  
Driver's Signature (if driver is not the policyholder) / Date & Time: [Signature] 06/06/2023  
Witnessed by Reporting Centre Personnel: [Signature]




Describe Circumstances of the Accident


Moderate traffic due to front vehicle  
Slow down & brake. I followed suit  
Vehicle SAMU 5279 R (Front) hit  
into my vehicle SJH 5839 Z rear  
portion.

Declaration

We declare the foregoing particulars are true in every respect.

  
\_\_\_\_\_  
Policyholder's Signature / Date &  
Time  
06/06/2023  
09:40am

  
\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date  
& Time  
06/06/2023  
09:40am

  
\_\_\_\_\_  
Witnessed by Reporting Centre  
Personnel



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SJH5939Z

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information

WIP No 10440  
Reg No/Reg Date SJH5939Z / 29/01/2019  
Date In/Mileage / 0  
Chassis No WDD2130422A5778425  
Engine No 27492031696421  
Make/Model MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE  
Colour/Trim 027 775 Iridium Sil/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	23/06/2023/ 13:24	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE :1900015593-04//05.06.2023 DRIVE IN/EXCESS :06.06.2023// TP CAR NO.: SMU5279R=CHINA TAIPING DATE IN/DATE SURVEY:23.06.2023//23.06.2023 RASUL-LKK DIRECT SETTLEMENT: JENNY LEW-CHINA TAIPING				
M BPNSUN SUNDRIES DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				15.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				380.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				960 1200.00
A BPIRES RESPRAY ON REAR BUMPER AND ACCIDENT AFFECTED AREA				800 1200.00
M REAR BUMPER <i>cut</i>	1.00	1587.48	00.00	1587.48
M REAR LOWER BUMPER <i>cut</i>	1.00	389.53	00.00	389.53
M REAR BUMPER CHROME MOULDING <i>cut</i>	1.00	402.10	00.00	402.10
M RIVET <i>cut</i>	2.00	5.34	00.00	10.68
M CTR BASIC MOUNTING FOR BUMPER <i>? XAN</i>	1.00	154.56	00.00	154.56
M RIVET <i>? XAN</i>	12.00	5.34	00.00	64.08
M REAR CROSS MEMBER <i>? XAN</i>	1.00	1039.80	00.00	1039.80

THIS IS NOT AN OFFICIAL TAX INVOICE  
ESTIMATE

*Resu*  
*Hp 2001008*  
*3 days*  
*23/06/23 @ 1425*  
*Resu by part*

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer  
Signature:  
Date:

Nett 6,443.23  
8% GST on 6443.23 515.46  
Total Payable 6,958.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SJH5939Z

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 10440  
Reg No/Reg Date SJH5939Z / 29/01/2019  
Date In/Mileage 23/06/2023/ 60811  
Chassis No WDD2130422A5778425  
Engine No 27492031696421  
Make/Model MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE  
Colour/Trim 027 775 Iridium Sil/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	02/08/2023/ 16:56	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
M BPNSUN POLICY NO/ACC DATE :1900015593-04//05.06.2023 DRIVE IN/EXCESS :06.06.2023// TP CAR NO.: SMU5279R=CHINA TAIPING DATE IN/DATE SURVEY:23.06.2023//23.06.2023 RASUL-LKK 14:30pm DIRECT SETTLEMENT: JENNY LEW-CHINA TAIPING				15.00
M BPNSUN SUNDRIES			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				960.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH-NEW BODY PANELS WITH REFINISH.			0.05	800.00
A BPIRES RESPRAY ON REAR BUMPER AND ACCIDENT AFFECTED AREA	1.00	1587.48	00.00	1587.48
X REAR BUMPER	1.00	389.53	00.00	389.53
X REAR LOWER BUMPER	1.00	402.10	00.00	402.10
X REAR BUMPR CHROME MOULDING	2.00	5.34	00.00	10.68
X RIVET	1.00	85.45	00.00	85.45
X LHR EXHAUST TIP BRACKET				

ESTIMATE

Finalization

3 Days

Confirmed & accepted by

8% GST on **Nett 4,630.24** **370.42**  
**Total Payable 5,000.66**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SJH5939Z

Vehicle & Document Information

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

WIP No 10440  
Reg No/Reg Date SJH5939Z / 29/01/2019  
Date In/Mileage 23/06/2023/ 60811  
Chassis No WDD2130422A5778425  
Engine No 27492031696421  
Make/Model MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE  
Colour/Trim 027 775 Iridium Sil/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	02/08/2023/ 16:55	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request  
M BPNSUN

POLICY NO/ACC DATE :1900015593-04//05.06.2023  
DRIVE IN/EXCESS :06.06.2023// TP CAR NO.: SMU5279R=CHINA TAIPING  
DATE IN/DATE SURVEY:23.06.2023//23.06.2023 RASUL-LKK 14:30pm  
DIRECT SETTLEMENT: JENNY LEW-CHINA TAIPING

X LHR EXHAUST TIP BRACKET *cm*

1.00 85.45 00.00 85.45

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

	Nett	85.45
8% GST on	85.45	6.84
	<b>Total Payable</b>	<b>92.29</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg