

(08/11/13) wef

ASS. REC. BY: Paul

REF:

W/SMR 23 005 703 / RVY 3

5021

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 3759Lat Workshop m/s KAH MOTORof ALEXANDRA RDInsured: SMR

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: SIK

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLD 3759L Yr Regn: 2016 / JUNType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA JAZZ 1.5 VTR CUT c.c. 1498Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 062754 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMHK58506X202899Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIZ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 31/05/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 12/06/23KAH MOTOR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPORT LHM7-28K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/05/2023 15:59 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	31/05/2023 13:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JALAN JURONG KECHIL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD3759L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN MEE CHOO
NRIC No	SXXXX502I
Email Address	doristan2009@gmail.com
Mobile Phone No	(Phone) +65-90095288
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Jazz
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	MR002827

DRIVER

Name of Driver	TAN MEE CHOO
NRIC No	SXXXX502I
Date Of Birth	26/03/1959
Occupation	Indoor

Contact Number	(Phone) +65-89220443
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEH B
No. Of Passenger (Including Driver)	-

Describe Circumstances of the Accident

I stopped my vehicle when traffic light turn red.
The bus (B) hit ~~on~~ my vehicle rear ~~part~~ portion.

Declaration

I/We declare the foregoing particulars are true in every respect.

2001

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Q

Witnessed by Reporting Centre
Personnel



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: SMRT BUSES LTD	Document No.	: SQT23001681	Page	1
	60 WOODLANDS INDUSTRIAL	Date	: 5. Jun 2023		
	PARK E4	Customer No.	: WZS001		
	SINGAPORE 757705	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: SLD3759L	Engine No	: L15B31021190		
Chassis No	: JHMGK5850GX202899	Date Time	: 5. Jun 2023 9:12:48 AM		
Model	: JAZZ 1.5VTIR CVT 16YM	Surveyor Name	:		
Owner's Name	: TAN MEE CHOO	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 31/5/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN MEE CHOO						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 31/05/2023						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: SMRT BUSES						
	TP VEH: SMB1427G						
68100-T5B-Z50ZZ	TAILGATE COMP <i>ht</i>	1	782.10	25	586.57	46.93	633.50
74440-T5A-003	WEATHERSTRIPTAILGATE <i>Xnn</i>	1	92.30	25	69.22	5.54	74.76
74800-T5A-J01	LOCK ASSYTAILGATE <i>Xnn</i>	1	91.10	25	68.32	5.47	73.79
75722-T5L-T01	EMBLEMRR. <i>u</i>	1	12.50	25	9.37	0.75	10.12
04715-T5B-000ZZ	FACERR.BUMPER <i>de</i>	1	554.00	25	415.50	33.24	448.74
71502-T5A-000	GARNISHR.RR.BUMPER <i>Xnn</i>	1	15.20	25	11.40	0.91	12.31
71507-T5A-000	GARNISHL.RR.BUMPER <i>Xnn</i>	1	15.20	25	11.40	0.91	12.31
71593-T5A-000	SPACERR.RR.BUMPER <i>u</i>	1	11.50	25	8.62	0.69	9.31
71598-T5A-000	SPACERL.RR.BUMPER <i>u</i>	1	11.50	25	8.62	0.69	9.31
91505-TM8-003	CLIP,BUMPER <i>u</i>	5	2.30	25	8.62	0.69	9.31
90107-S9V-A01	BOLTRR.BUMPER STOPPER <i>u</i>	2	4.80	25	7.20	0.58	7.78
66100-TAR-T10ZZ	PANEL COMPRR. <i>Requ</i>	1	342.90	25	257.17	20.57	277.74
84640-T5A-003ZA	LINING ASSY,RR.PANEL <i>Xnn</i>	1	60.80	25	45.60	3.65	49.25
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>?Xnn</i>	1	320.00		320.00	25.60	345.60
33500-T5A-J02	TAILLIGHT ASSY,R. <i>X nn</i>	1	258.40	25	193.80	15.50	209.30
33550-T5A-J02	TAILLIGHT ASSYL. <i>X nn</i>	1	258.40	25	193.80	15.50	209.30
Sum Item					2215.21	177.22	2,392.43
BOSUN	SUNDRIES	1	100.00	30	100.00	8.00	108.00

Printed on 5/6/2023 9:27:06 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SMRT BUSES LTD
60 WOODLANDS INDUSTRIAL
PARK E4
SINGAPORE 757705

Registration No : SLD3759L
Chassis No : JHMGK5850GX202899
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : TAN MEE CHOO
Ins Policy No :
Date of Accident : 31/5/2023

Document No. : SQT23001681
Date : 5. Jun 2023
Customer No. : WZS001
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B31021190
Date | Time : 5. Jun 2023 9:12:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	150	280.00	22.40	302.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00	150	280.00	22.40	302.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	500	560.00	44.80	604.80
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00	500	560.00	44.80	604.80
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	100	650.00	52.00	702.00
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00	100	120.00	9.60	129.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3900.00	1950	3900.00	312.00	4212.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3120.00	1040	3120.00	249.60	3369.60
Sum Labor					9570.00	765.60	10,335.60

Survey By

Date & Time

Excess

Status

Signature

Issue - H. 2000 68

12/06/23 0140

6 days

Paul

Resy 54 point

Total Amount 11,785.21 942.82 12,728.03

Total (Inclusive of GST) 12,728.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 5/6/2023 9:27:06 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0034678 / SMRT BUSES LTD
Chassis No: JHMGK5850GX202899
License No: SLD3759L
Mileage: 62754
Engine No: L15B31021190

Document No: SVO23023353
Printed By: IVANTEO
Order Date: 12. June 2023
Order Time: 2:31:55 PM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	8% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN MEE CHOO OWNER INSURER: TOKIO MARINE ACC DATE: 31/05/2023 SURVEYED BY: RASUL LKK DATE: REF NO: TP INSURER: SMRT BUSES TP VEH: SMB1427G SUPPLEMENTARY PART						
68100-T5B-Z50ZZ	TAILGATE COMP	1	782.10	25	586.57	46.93	633.50
75722-T5L-T01	EMBLEMRR.	1	12.50	25	9.37	0.75	10.12
04715-T5B-000ZZ	FACERR.BUMPER	1	554.00	25	415.50	33.24	448.74
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.69	9.31
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.69	9.31
91505-TM8-003	CLIP,BUMPER	5	2.30	25	8.62	0.69	9.31
90107-S9V-A01	BOLTRR.BUMPER STOPPER	1	4.80	25	3.60	0.29	3.89
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER <i>suppl nec</i>	1	12.30	25	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER <i>suppl nec</i>	2	7.60	25	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5 <i>suppl nec</i>	1	9.10	25	6.82	0.55	7.37
	SUM PARTS:				1,068.34	85.48	1,153.82
BOSUN		1	30.00		30.00	2.40	32.40
	SUNDRIES						
BML02I		1	150.00		150.00	12.00	162.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R		1	150.00		150.00	12.00	162.00
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BC012R		1	500.00		500.00	40.00	540.00
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R		1	500.00		500.00	40.00	540.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BKTG02R		1	650.00		650.00	52.00	702.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BODAMKIT		1	100.00		100.00	8.00	108.00
	WINDSCREEN DAM KIT.						
BKRP02S	1729	1	1,950.00		1,950.00	156.00	2,106.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
BP05R	1718	1	1,040.00		1,040.00	83.20	1,123.20
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
	SUM LABOUR:				5,070.00	405.60	5,475.60
	TOTAL SGD				6,138.34	491.08	6,629.42

Total Payable (SGD)

6,629.42



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0034678 / SMRT BUSES LTD

Chassis No: JHMGK5850GX202899

License No: SLD3759L

Mileage: 62754

Engine No: L15B31021190

Document No: SVO23023353

Printed By: IVANTEO

Order Date: 12. June 2023

Order Time: 2:31:55 PM

Service Advisor: IVAN TEO BOON KIAT

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0034678 / SMRT BUSES LTD
Chassis No: JHMGK5850GX202899
License No: SLD3759L
Mileage: 62754
Engine No: L15B31021190

Document No: SVO23023353
Printed By: IVANTEO
Order Date: 12. June 2023
Order Time: 2:31:55 PM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN MEE CHOO						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 31/05/2023						
	SURVEYED BY: RASUL LKK						
	DATE:						
	REF NO:						
	TP INSURER: SMRT BUSES						
	TP VEH: SMB1427G						
	SUPPLEMENTARY PART						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1.	12.30	25.	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2.	7.60	25.	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5	1.	9.10	25.	6.82	0.55	7.37
	SUM PARTS:				27.44		

GST Amount is calculated from individual line(s)