

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: SMRT BUSES LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Document No.	: SQT23001681	Page	1
Registration No	: SLD3759L	Date	: 5. Jun 2023	Customer No.	: WZS001
Chassis No	: JHMGK5850GX202899	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15B31021190
Model	: JAZZ 1.5VTIR CVT 16YM	Date Time	: 5. Jun 2023 9:12:48 AM	Surveyor Name	:
Owner's Name	: TAN MEE CHOO	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 31/5/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN MEE CHOO OWNER INSURER: TOKIO MARINE ACC DATE: 31/05/2023 SURVEYED BY: DATE: REF NO: TP INSURER: SMRT BUSES TP VEH: SMB1427G						
68100-T5B-Z50ZZ	TAILGATE COMP	1	782.10	25	586.57	46.93	633.50
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	5.54	74.76
74800-T5A-J01	LOCK ASSYTAILGATE	1	91.10	25	68.32	5.47	73.79
75722-T5L-T01	EMBLEMRR.	1	12.50	25	9.37	0.75	10.12
04715-T5B-000ZZ	FACERR.BUMPER	1	554.00	25	415.50	33.24	448.74
71502-T5A-000	GARNISHR.RR.BUMPER	1	15.20	25	11.40	0.91	12.31
71507-T5A-000	GARNISHL.RR.BUMPER	1	15.20	25	11.40	0.91	12.31
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.69	9.31
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.69	9.31
91505-TM8-003	CLIP,BUMPER	5	2.30	25	8.62	0.69	9.31
90107-S9V-A01	BOLTRR.BUMPER STOPPER	2	4.80	25	7.20	0.58	7.78
66100-TAR-T10ZZ	PANEL COMPRR.	1	342.90	25	257.17	20.57	277.74
84640-T5A-003ZA	LINING ASSY,RR.PANEL	1	60.80	25	45.60	3.65	49.25
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	25.60	345.60
33500-T5A-J02	TAILLIGHT ASSY,R.	1	258.40	25	193.80	15.50	209.30
33550-T5A-J02	TAILLIGHT ASSYL.	1	258.40	25	193.80	15.50	209.30
				Sum Item	2215.21	177.22	2,392.43
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00

Printed on 5/6/2023 9:27:06 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: SMRT BUSES LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Document No.	: SQT23001681	Page	2
Registration No	: SLD3759L	Date	: 5. Jun 2023	Customer No.	: WZS001
Chassis No	: JHMGK5850GX202899	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15B31021190
Model	: JAZZ 1.5VTIR CVT 16YM	Date Time	: 5. Jun 2023 9:12:48 AM	Surveyor Name	:
Owner's Name	: TAN MEE CHOO	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 31/5/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	22.40	302.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	22.40	302.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		560.00	44.80	604.80
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00		560.00	44.80	604.80
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	52.00	702.00
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00		120.00	9.60	129.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3900.00		3900.00	312.00	4212.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	3120.00		3120.00	249.60	3369.60
Sum Labor					9570.00	765.60	10,335.60

Survey By							
Date & Time					Total Amount	11,785.21	942.82
Excess					Total (Inclusive of GST)		12,728.03
Status							
Signature							

Printed on 5/6/2023 9:27:06 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.