



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23005707/Avy3m4 Date: 12/07/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 9132T	Veh. Inspected	SKE 7899X	
Policy No.	D23MTPV01002493	Coverage (\$)	0.00	
Claim No.	CMTD2302271/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	06/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2040452A551496	Colour	BLACK	
Odometer	189486 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40R18	GOODTRIP	6 mm	
L/H Front Tyre	245/40R18	GOODTRIP	6 mm	
R/H Rear Tyre	245/40R18	GOODTRIP	6 mm	
L/H Rear Tyre	245/40R18	GOODTRIP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/06/2023	Inspection Date	06/06/2023	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		