



Vehicle number SKE7899X
Make / Model MERCEDES C180
Chassis number WDD2040452A551496
Accident date 5/6/23
Reference 2306-06

TP Seng
Veron.

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
2	REAR BUMPER RETAINER <i>LH dng</i>	108.20 <i>54.20</i>
2	REAR BUMPER REINFORCEMENT <i>Defect</i>	971.30 <i>✓</i>
4	REAR BUMPER PDC SENSOR <i>2 pieces dng</i>	1724.80 <i>560</i>
2	REAR BUMPER CARRIER LH/RH <i>new</i>	92.00 <i>+</i>
1	REAR BUMPER CARRIER CENTER <i>new</i>	182.20 <i>✓</i>
2	TAILLAMP <i>3 new</i>	1777.60 <i>+</i>
2	TAILLAMP BRACKET	195.80 <i>+</i>
1	END PANEL <i>new</i>	1733.60 <i>+</i>
1	END PANEL TOP GARNISH <i>new</i>	163.90 <i>+</i>
		6949.40
Less 10%		694.94
		6254.46
PARTS REPLACEMENT - SPECIAL NETT		
1	REAR BUMPER (AFTER MARKET) <i>Defect</i>	1800.00 <i>1400</i>
1	REAR BUMPER DIFFUSER (AFTER MARKET) <i>Defect</i>	900.00 <i>700</i>
1 SET	REAR BUMPER CLIP <i>new</i>	30.00 <i>+</i>
1 SET	END PANEL TOP GARNISH CLIP <i>new</i>	50.00 <i>+</i>
Subtotal		2780.00
		9034.46
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTNING SYSTEM	80.00 <i>30</i>
2	REMOVE & REPLACE REVERSE SENSOR	150.00 <i>50</i>
3	REMOVE & REFIT TRIMS AND GARNISHES	150.00 <i>740</i>
4	PANEL BEATING ON AFFECTED AREAS	800.00 <i>300</i>
5	SPRAY PAINTING ON AFFECTED AREAS	800.00 <i>300</i>
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>+</i>
Subtotal		2130.00
Grand total		11164.46

2130

Adrian L
2/s 06/06/23
032yo

total: 4174.26
L/s: 3.3K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: