

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23005709/RNY3Q2**Date:** 06/07/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP322038
Claimant Vehicle No :	SMU7903J	Insured Vehicle No :	SNG110M
Date of Loss:	20/05/2023	Nature of Claim:	TP
		Claim No:	MPC04278

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7903J		
Make & Model:	SKODA OCTAVIA, 1.4 AMBITION TSI (A)	Engine No:	CZDA63202
Reg. Date:	28/08/2020 (Man. Year: 2019)	Chassis No:	TMBBC7NE8L0038187
Colour:	Brown	Odometer:	40634 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,105.41	2,320.06	3,785.35	62.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,880.00	10,180.00	700.00	6.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,985.41	12,500.06	4,485.35	26.41
+ GST 8.00/8.00% (S\$)	1,358.83	1,000.00	358.83	26.41
Nett Amount (S\$)	18,344.24	13,500.06	4,844.18	26.41

INSPECTION

Date of Assignment:	06/06/2023	
Date Inspected:	08/06/2023	Inspected At: Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	143	SKODA OCTAVIA 1.4 AMBITION TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU7903J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER LHS FENDER	Bent	845.49 FS	*845.49 FS
2	4		*RIVETTED CAP NUT	Necessary	10.56 FS	*10.56 FS
3	1		*FENDER -B LHS FENDER BRACKET	Not Necessary	90.69 FS	*- FS
4	1		*REAR VIEW LHS MIRROR HOUSING	Cracked	1,351.30 FS	*1,351.30 FS
5	1		*CAP FOR RE LHS MIRROR COVER	Repair	119.67 FS	*- FS
6	1		*MIRROR GLA LHS MIRROR GLASS	Not Necessary	245.41 FS	*- FS
7	1		*WINDOW SIO LHS FRT DOOR GLASS OUTER MLDG	Scratched	67.78 FS	*67.78 FS
8	1		*UNBEKANNT LHS REAR DOOR	Repair	3,168.61 FS	*- FS
9	1		*DOOR SEAL	Not Necessary	102.89 FS	*- FS
10	1		*ALU-LAMIN INSULATION DOOR INSULATION	Not Necessary	43.66 FS	*- FS
11	6		*CLIP	Not Necessary	12.30 FS	*- FS
12	4		*UNBEKANNT RIVET NUT	Not Necessary	2.12 FS	*- FS
13	1		*FOIL LHR FENDER FOIL	Necessary	44.93 FS	*44.93 FS
Total Parts (S\$)						6,105.41 2,320.06

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING FENDER	New	480.00	480.00
3	LABOUR	New	4,200.00	4,200.00
4	SPRAY PAINT	New	4,800.00	4,800.00
5	TRANSFER DOOR MECHANISM	New	840.00	420.00
6	SPRAY MIRROR COVER	New	280.00	280.00
Gross Labour Cost (S\$)			10,880.00	10,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >