

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 13 Jun 2023

**Preliminary Advice**

Insured Vehicle No	: SKM8977E	Accident Date	: 03/06/2023
TP Vehicle No	: SJN9374U	Assignment Date	: 06/06/2023
Make	: HYUNDAI HD AVANTE	Est. Duration of Repair	: 4
Date of Inspection	: 07/06/2023		
Inspection At	: AUTHORIZE WORKSHOP PTE LTD 160 SIN MING DRIVE #03-19, SIN MING AUTOCITY, SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,463.29
Revised Amount	:S\$	2,946.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,946.36
Lump Sum Repair	:S\$	2,350.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	1,897.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,103.00

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.