

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/06/2023
Vehicle Reg. No.:	SHC2521P	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	13/12/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2F93235	Chassis No:	JTDKB3FU303090161
Odometer:	358297 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	10,300.77
Miscellaneous Items	11.00
Labour	2,690.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,001.77
+ GST 8.00% (S\$)	1,040.14
Nett Amount (S\$)	14,041.91

This claim is handled by: **CHIANG LIAT CHOON**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 Jun 2023)**Parts:** 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHC2521P)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	25.00	0.00	de- *586.18 FL
2	1		*FRONT BUMPER REINFORCEMENT	25.00	0.00	x *812.89 FL
3	2		*FRONT BUMPER REINFORCEMENT ABSORBER LH/RH	25.00	0.00	x *231.40 FL
4	1		*FRONT BUMPER CENTRE GRILLE	25.00	0.00	7 *301.90 FL
5	1		*FRONT BUMPER LOWER GRILLE	25.00	0.00	x *193.18 FL
6	10		*FRONT BUMPER CLIPS	25.00	0.00	net *22.00 FL
7	1		*FRONT BUMPER GARNISH RH	25.00	0.00	? *90.00 FL
8	2		*FRONT BUMPER RETAINER LH/RH	LHX 25.00	0.00	RH de- *181.50 FL
9	1		*FRON SUPPORT RAD TOP	25.00	0.00	x *278.68 FL
10	1		*FRONT SUPPORT RAD LOWER	25.00	0.00	x *393.20 FL
11	2		*FRONT SUPPORT RAD LH/RH	LHX 25.00	0.00	RH? *152.20 FL
12	1		*HEADLAMP RH	25.00	0.00	net *2,735.28 FL
13	1		*FRONT FENDER RH	25.00	0.00	bt- *1,111.93 FL
14	1		*FRONT FENDER EMBLEM RH	25.00	0.00	net *86.50 FL
15	1		*FRONT FENDER SHIELD RH	25.00	0.00	fn- *198.50 FL
16	1		*FRONT WING MIRROR RH	25.00	0.00	bnv- *139.10 FL
17	1		*FRONT WING MIRROR COVER RH	25.00	0.00	mis- *14.90 FL
18	1		*FRONT DOOR PANEL RH	25.00	0.00	bt- *1,264.00 FL
19	1		*FRONT DOOR HINGE UPPER LH/RH	25.00	0.00	? *91.20 FL
20	1		*FRONT DOOR HINGE LOWER RH	25.00	0.00	? *91.20 FL
21	1		*FRONT DOOR CHECK RH	25.00	0.00	? *153.52 FL
22	1		*FRONT SUSPENSION ARM RH	25.00	0.00	? *637.50 FL
23	1		*FRONT BALL JOINT RH	25.00	0.00	x *199.80 FL
24	1		*FRONT TIE ROD END RH	25.00	0.00	x *159.30 FL
25	1		*FRONT WHEEL ALU RIM RH	25.00	0.00	de- *1,555.00 FL
26	1		*FRONT TYRE RH	80% 0	0.00	net *216.00 FS
27	1		*FRONT KNUCKLE STRG RH	25.00	0.00	? *580.80 FL
28	1		*FRONT SHOCK ABSORBER RH	25.00	0.00	? *401.80 FL
29	1		*FRONT SHOCK ABSORBER TOP MTG RH	25.00	0.00	x *196.20 FL
30	1		*FRONT WIPER SPARE TANK	25.00	0.00	x *486.70 FL
31	1		*FRONT DOOR COMFORT LOGO STICKER	0	0.00	net *75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,637.36
- List Item Discount on L Items (\$\$)	3,336.59
Total Parts (\$\$)	10,300.77

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 1,250.00
2	SPRAY PAINTING	New	750 900.00
3	REMOV/REFIX AIR CON AND CHARGE GAS	New	X 120.00
4	CHECK WIRING AND LIGHTING	New	30 60.00
5	RESET FRONT WHEEL ALIGNMENT	New	80 90.00
6	REMOVE/ REFIX FRONT UNDER CARRIAGE	New	7 120.00
7	TOWING FEE	New	towing receipt 60.00
8	REMOVE.REFIX DOOR PART FRT	New	60 90.00
Gross Labour Cost (\$\$)			2,690.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Tarplin 97495749
'wp' 6/6/23 @ 330
1/5 Resurvey after repair
3-4 days
tarplin @ 1/6/23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: