

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/06/2023
Vehicle Reg. No.:	SHC2521P	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	13/12/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2F93235	Chassis No:	JTDKB3FU303090161
Odometer:	358297 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	10,300.77
Miscellaneous Items	11.00
Labour	2,690.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,001.77
+ GST 8.00% (S\$)	1,040.14
Nett Amount (S\$)	14,041.91

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2023)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2521P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	25.00	0.00	de- *586.18 FL
2	1		*FRONT BUMPER REINFORCEMENT	25.00	0.00	x *812.89 FL
3	2		*FRONT BUMPER REINFORCEMENT ABSORBER LH/RH	25.00	0.00	x *231.40 FL
4	1		*FRONT BUMPER CENTRE GRILLE	25.00	0.00	7 *301.90 FL
5	1		*FRONT BUMPER LOWER GRILLE	25.00	0.00	x *193.18 FL
6	10		*FRONT BUMPER CLIPS	25.00	0.00	net *22.00 FL
7	1		*FRONT BUMPER GARNISH RH	25.00	0.00	? *90.00 FL
8	2		*FRONT BUMPER RETAINER LH/RH	LHX 25.00	0.00	RH de- *181.50 FL
9	1		*FRON SUPPORT RAD TOP	25.00	0.00	x *278.68 FL
10	1		*FRONT SUPPORT RAD LOWER	25.00	0.00	x *393.20 FL
11	2		*FRONT SUPPORT RAD LH/RH	LHX 25.00	0.00	RH? *152.20 FL
12	1		*HEADLAMP RH	25.00	0.00	net *2,735.28 FL
13	1		*FRONT FENDER RH	25.00	0.00	bt- *1,111.93 FL
14	1		*FRONT FENDER EMBLEM RH	25.00	0.00	net *86.50 FL
15	1		*FRONT FENDER SHIELD RH	25.00	0.00	fn- *198.50 FL
16	1		*FRONT WING MIRROR RH	25.00	0.00	brv- *139.10 FL
17	1		*FRONT WING MIRROR COVER RH	25.00	0.00	mis- *14.90 FL
18	1		*FRONT DOOR PANEL RH	25.00	0.00	bt- *1,264.00 FL
19	1		*FRONT DOOR HINGE UPPER RH	25.00	0.00	? *91.20 FL
20	1		*FRONT DOOR HINGE LOWER RH	25.00	0.00	? *91.20 FL
21	1		*FRONT DOOR CHECK RH	25.00	0.00	? *153.52 FL
22	1		*FRONT SUSPENSION ARM RH	25.00	0.00	? *637.50 FL
23	1		*FRONT BALL JOINT RH	25.00	0.00	x *199.80 FL
24	1		*FRONT TIE ROD END RH	25.00	0.00	x *159.30 FL
25	1		*FRONT WHEEL ALU RIM RH	25.00	0.00	de- *1,555.00 FL
26	1		*FRONT TYRE RH	80% 0	0.00	protected *216.00 FS
27	1		*FRONT KNUCKLE STRG RH	25.00	0.00	? *580.80 FL
28	1		*FRONT SHOCK ABSORBER RH	25.00	0.00	? *401.80 FL
29	1		*FRONT SHOCK ABSORBER TOP MTG RH	25.00	0.00	x *196.20 FL
30	1		*FRONT WIPER SPARE TANK	25.00	0.00	x *486.70 FL
31	1		*FRONT DOOR COMFORT LOGO STICKER	0	0.00	net *75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,637.36
- List Item Discount on L Items (S\$)	3,336.59
Total Parts (S\$)	10,300.77

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 1,250.00
2	SPRAY PAINTING	New	750 900.00
3	REMOV/REFIX AIR CON AND CHARGE GAS	New	X 120.00
4	CHECK WIRING AND LIGHTING	New	30 60.00
5	RESET FRONT WHEEL ALIGNMENT	New	80 90.00
6	REMOVE/ REFIX FRONT UNDER CARRIAGE	New	120.00
7	TOWING FEE	New	towing receipt 60.00
8	REMOVE.REFIX DOOR PART FRT	New	60 90.00
Gross Labour Cost (\$\$)			2,690.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Tanpin 97495749
 'wp' 6/6/23 @ 330
 1/5 Resurvey after repair
 3-4 days
 tanpin @ (handwritten)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: