## AIR DETAILS

ference

Version: 1.0 (Last Synchronised: 06 Jun 2023) t Source: MRM-SG TOYOTA PRIUS TAXI 1.8 (A) (Catalogue: Merimen Singapore 1.0)

144 arts: (Price-denominated Standard List) Repairer's abour:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Print Code:

Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Estimates on			%Disc %	6Depr	Amount	
No. Qty Part No.	Particulars			and de-	*586,18 FL	
	**************************************	4	25.00	0.00	*812.89 FL	
1 1	*FRONT BUMPER *FRONT BUMPER REINFORCEMENT		25.00	0.00 NY X	*231,40 FL	-
2 1	*FRONT BUMPER REINFORCEMENT ABSOBER	I I H/RH	25.00	0.00 NU X		
3 2	*FRONT BUMPER CENTRE GRILLE		25.00	0.00 MY X	*301.90 FL	•
4 1	*FRONT BUMPER CENTRE GRILLE  *FRONT BUMPER LOWER GRILLE		25.00	0.00 m/x	*193.18 FL	
5 1		.*	25.00	0.00 191	*22.00 FL	
6 10	*FRONT BUMPER CLIPS		25.00 25.00	0.00 nn	*90.00 FL	0.16
7 1	*FRONT BUMPER GARNISH RH	ZHX"	25.00	0.00 RH du-		4011
8 2	*FRONT BUMPER RETAINER LH/RH		25.00	0.00 nn X	*278.68 FL	
9 1	*FRON SUPPORT RAD TOP		25.00	0.00 WY X	*393.20 FL	
10 1	*FRONT SUPPORT RAD LOWER	ZHKN	25.00	0.00 RAXV	*152.20 FL	÷
11 2	*FRONT SUPPORT RAD LH/RH	Second Second	25.00	0.00 04-	2,735.28 FL	¥.
12 1	*HEADLAMP RH		25.00	0.00 /1-*	1,111.93 FL	*
13 1	*FRONT FENDER RH	**	25.00	0.00 war	*86.50 FL	Λ.
14 1	*FRONT FENDER EMBLEM RH	A	25.00	0.00 m	*198.50 FL	
15 1	*FRONT FENDER SHIELD RH	repeated / <del>2.70-</del> 10	25.00	0.00 bre		
16 1	*FRONT WING MIRROR RH	repeated 14140	25.00	0.00 0015	*14.90 FL	
17 1	*FRONT WING MIRROR COVER RH	repeated	25.00		1,264.00 FL	
18 1	*FRONT DOOR PANEL RH		25.00	0.00 8 49	*91.20 FL	
19 1	*FRONT DOOR HINGE UPPERL RH		25.00		7 *91,20 FL	
20 1	*FRONT DOOR HINGE LOWER RH	10. C C C C C C C C.	25.00		*153.52 FL	
21 1	*FRONT DOOR CHECK RH		25.00	0.00 NY X	*637.50 FL	
22 1	*FRONT SUSPENSION ARM RH		25.00		*199.80 FL	
23 1	*FRONT BALL JOINT RH		25.00	0.00 MX	*159.30 FL	
24 1	*FRONT TIE ROD END RH  *FRONT WHEEL ALU RIM RH		25.00	0.00 14/*		•
25 1	*FRONT TYRE RH	ે કેવ		0.00 pented		172.80
26 1	*FRONT KNUCKLE STRG RH		25.00	0.00 NUX	*580,80 FL	1/2.0
27 1	*FRONT SHOCK ABSORBER RH		25.00	0.00 44 8	*401.80 FL	
28 1	*FRONT SHOCK ABSORBER TOP MTG RH		25.00	0.00 AN X		
29 1	*FRONT SHOCK ABSORBER TOP MIG KIT		25.00	× NN 00.0		
30 1	*FRONT DOOR COMFORT LOGO STICKER		23.00		*75.00 FS	
31 1 F=Franchise part, S=SpcN	TARTOR SCIENCES SEE		<u> </u>	0.00 / 0.00	75,00 FS	
i –i idiiciise part, 3–3pcm		Sub Total (S\$)		4.5	3,637.36	
	1590,000	- List Item Discount on L Items (S\$)			3,336.59	
	WILLOW POUR	1				
	mirror py 1390.10 prov mirror py 1390.10 prov	Total Parts (S\$)		10	,300.77	

Report was unsubmitted during this print-out, Generated using **Merimen e-Claims IEAS** 

9182 · 14 25% 6886 · 60 3N 247-80

1:26 AM	Merimen e-Claims				
mates on Miscellaneous Items  Qty Particulars	Α	Amount			
scellaneous Items 1 OD/TP Case (Insurer)	·	11.00			
	Sub Total (S\$)	11.00			
	1	Í			
Estimates on Labour  No Particulars	Lab.Type A	Amount			
Labour Items	New 700 1				
1 PANEL BEATING 2 SPRAY PAINTING	New 750				
3 REMOV/REFIX AIR CON AND CHARGE GAS 4 CHECK WIRING AND LIGHTING	New Ny X New 3Q	60.00			
5 RESET FRONT WHEEL ALIGNMENT 6 REMOVE/ REFIX FRONT UNDER CARRIAGE	New So	90.00			
7 TOWING FEE 8 REMOVE, REFIX DOOR PART FRT	fourly recept New / Will	90.00			
	1/002	690.00			

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taylin 97495749

247.80

(WP) 6/6/73 e 330

(/5 Normy yterreper 1680

1 3 Ddays

taylin e/blantown (157050

"4day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: