



SHIFTER AUTO GARAGE PTE. LTD.

Co. Reg. No: 202230804K

3016 Bedok North Avenue 4

#07-04 Eastech

Singapore 489947

Email: shifterauto.sag@gmail.com

## TAX INVOICE

Liberty Insurance Pte. Ltd.

6221 8611

Invoice No. : SAG2023 57 02  
Invoice Date : February 11, 2023  
Vehicle No. : SLJ 9262 U  
Make & Model : HONDA FIT 1.3G A  
Chassis No. : GE61119657  
Mileage : -  
Terms : Due within 90 days

NO.	DESCRIPTION	QUANTITY	PER UNIT (SGD)	AMOUNT (SGD)
1	To Carry Out Repair & Respray on Accident Corresponding to Supply on Spare Parts & Labour Charges	1	27,850.00	27,850.00

<b>GRAND TOTAL:</b>	<b>\$27,850.00</b>
Amount Paid	\$0.00
Balance Due	\$27,850.00



Signature/Company Stamp

*I agree to the price as listed above and affirm that the goods are received in good condition.*

# CARS FOR RENT (2016) PTE LTD

Mailing Address:  
10 Kaki Bukit Ave 4 #09-60 Premier@Kaki Bukit, Singapore 415874  
Tel Nos.: +65 6970 9119 / 6789 5155  
Co. Reg'n No.: 201609732N  
GST Reg'n No.: 201609732N

Tax Invoice #: E2210233  
Date: 28-10-22

Bill To:

Shifter Auto Garage Pte Ltd  
For the account of:  
Kwek Ah Lam  
S1107223B  
APT Blk 138 Jalan Bukit Merah  
#10-1396

Ship To:

Shifter Auto Garage Pte Ltd  
For the account of:  
Kwek Ah Lam  
S1107223B  
APT Blk 138 Jalan Bukit Merah  
#10-1396

Description	Amount	Job No.
Vehicle Rental for Period 11.10.2022 to 27.10.2022 (Billing for days 16 X \$120.00/per day) (Vehicle No.: SJL9262U)	\$1,920.00	SJS1930R SR

④

Your Order #: 20840

		Terms: Net 30th after	GST:	\$125.61
COMMENT	CODE	RATE	GST SALE AMOUNT	Total Inv Amt: \$1,920.00
	SR	7%	\$125.61 \$1,794.39	Amount Applied: \$0.00
				Balance Due: \$1,920.00



# CARS FOR RENT (2016) PTE LTD

10 Kaki Bukit Ave 4 #09-60 Premier @ Kaki Bukit Singapore 415874

Tel: 6970 9119 Fax: 6970 9961

Website: www.carsforrent2016.com

No: 20840

SV SAG

ROC/GST No: 201609732N

## VEHICLE RENTAL AGREEMENT

<b>HIRER'S PARTICULAR</b>		Vehicle No: <u>SJS1930R</u>		Replace Veh No: <u>SJL 92624</u>	
Name: (as in I/C) <u>Kuek Ah Lam</u>		Mileage out:			
Email:		Make & Model: <u>Toyota Altis</u> Auto / Manual			
NRIC/PASSPORT No: <u>S1107223B</u>		OUT: Date <u>11/10/2022</u> Time: <u>1225hrs</u>			
Date of Birth: <u>16/3/1955</u>		<b>HIRE PERIOD</b>			
Address (Res): <u>APT B1K 138 Jalan Bukit Merah</u> <u>#10-1346 S(160138)</u>		OWN DAMAGE CLAIM Excess S\$ <u>2,000</u>			
Driving Licence No: <u>S1107223B</u> D/L Type: <u>Local</u> / International		THIRD PARTY CLAIM Excess S\$ <u>1,500</u>			
Issue Date: <u>01 Apr 2003</u>		<b>CHARGES</b>			
Tel: (O) _____ HP _____		Daily <u>16</u> @\$ <u>120.00</u> per day <u>1,920</u> <u>00</u>			
<b>Company Name:</b> _____		Weekly @\$ _____ per week			
Company UEN: _____		Monthly @\$ _____ per month			
Company Address: _____		Others @\$ _____			
<b>ADDITIONAL DRIVER'S PARTICULARS</b>		Delivery Service			
Name: (as in I/C) _____		GST			
NRIC/PASSPORT No: _____		<b>SUB-TOTAL \$</b>			
Date of Birth: _____		<b>PETROL LEVEL</b>			
Address (Res): _____		Out E <u>1/4</u> 1/2 3/4 F			
Driving Licence No: _____ D/L Type: Local / International		In E 1/4 1/2 3/4 F			
Issue Date: _____		EXTENSION			
Tel: (O) _____ HP _____		Misc.			
<b>VEHICLE CHECK LIST</b>		GST <u>Incl 7%</u>			
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>RIGHT</p> </div> <div style="text-align: center;"> <p>FRONT</p> </div> <div style="text-align: center;"> <p>TOP</p> </div> <div style="text-align: center;"> <p>LEFT</p> </div> </div> <p>BACK</p>		<b>TOTAL CHARGES</b> <u>1,920</u> <u>00</u>			
INDICATE: DENTS S - SCRATCHES A - ACCIDENTS		Rented out by:			
		Hirer's Signature			
		Addition Driver's Signature _____			

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/ credit card for payment, I agree that all amount payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CARS FOR RENT (2016) PTE LTD in connection with this agreement is true.

### \* IMPORTANT

- ONLY PERSON ABOVE 22 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN ABOVE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY AND BE RESPONSIBLE FOR THE INSURANCE EXCESS. IF THERE IS BODILY INJURIES, POLICE REPORT MUST BE MADE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF CARS FOR RENT (2016) PTE LTD

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVE" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CARDS FOR RENT (2016) PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	HIRER'S SIGNATURE
<u>27/10/22</u>					



# PRINCE TOWING SERVICES

CO REG NO: 53405980E

PRINCE TOWING SERVICES@GMAIL.COM / +65 9222 7993

NO. 7723

DATE: 11/10/22

M/S

VEHICLE NO

FROM

TO

REMARKS

SHIFTEN AUTO GARAGE

S5L 9282U

138 Bukit Merah RD

Piermont 02-24

MODEL

CALL TIME

TIME ARRIVAL


ARRIVAL WORKSHOP

FH

1030

1110

1140



- ☐ CHANGE TYRES/PATCH TYRES
- ☒ ACCIDENT
- ☐ USE CAR CARRIER
- ☐ LOADED
- ☐ BASEMENT/MULTI CARPARK
- ☐ LOW BODY KIT/LOW SPOILER
- ☐ OPEN DOOR
- ☐ JUMP START
- ☐ USING KING DOLLEY
- ☐ DISMANTLE BRAKE/SHAFT
- ☐ CRANE UP/WINCH OUT

AMOUNT S\$

601

RECEIVED BY

PRINCE TOWING

SHEN





# PRINCE TOWING SERVICES

CO REG NO: 53405980E

PRINCETOWING.SERVICES@GMAIL.COM/ +65 9222 7993



NO. 7727

DATE: 11/10/22

SHIFTER AUTO GARAGE P/L

M/S

VEHICLE NO

FROM

TO

REMARKS

MODEL

CALL TIME

TIME ARRIVAL

ARRIVAL WORKSHOP


717

1230

1425

1510

2WAY A/R



☐ CHANGE TYRES/PATCH TYRES ☐ ACCIDENT

☐ LOADED

☐ BASEMENT/MULTI CARPARK

☐ LOW BODY KIT/LOW SPOILER

☐ JUMP START

☐ USING KING DOLLEY

☐ DISMANTLE BRAKE/SHAFT

☐ CRANE UP/WINCH OUT

AMOUNT S\$

100-

SHEN

RECEIVED BY

PRINCE TOWING

# ALLIED AUTO APPRAISAL

22 Upper Serangoon Crescent #16-53 Singapore 534025

Company Registration No. 53127785B

**Our Ref: Allied/TP/22-10009**

Repairer : Shifter Auto Garage Pte Ltd  
Address of Inspection  
3016 Bedok North #07-04 Eastech  
Singapore 489947

**Veh No** : **SJL 9262 U**  
Date Report : **7-Feb-23**  
Date of Accident : **10-Oct-22**  
Date of Survey : **11-Oct-22**

## VEHICLE PARTICULARS & CONDITION

Make & Model	: Honda Fit 1.3G A	Date of Registration	: 16-Dec-08
Engine No	: L13A4131608	Engine c.c.	: 1339 cc
Chassis No	: GE61119657	COE Expiry Date	: 15-Dec-23

## CONDITION OF VEHICLE

General Condition	: Good	Modification	: No
Steering	: Serviceable	Air-Conditioner	: Yes
Handbrake	: Serviceable	Footbrake	: Serviceable
Wing Mirror	: Yes	Paint Work	: Good

## CONDITION OF TYRES (The below values represent the remaining tyre treads depth)


Front Tyre Size	: 185/60R15	Rear Tyre Size	: 185/60R15
Front Left Side	6mm Habilead	Rear Left Side	6mm Habilead
Front Right Side	6mm Habilead	Rear Right Side	6mm Habilead

## GENERAL DESCRIPTION OF DAMAGE

The inspected vehicle sustained damage at the **FRONT & REAR** portion.

During visual inspection, our surveyor noted that the bonnet, front bumper, headlamps, tailgate, rear bumper, taillamps, spare tyre panel and among other parts were affected.

All stated damage is subject to consistency of the accident reports.



## Repairer Estimate

Parts	: 31,485.00
Nett Item	: 2,500.00
Labour	: 8,340.00
Total	: #####

## Our Recommendation

Parts :	25,188.00
Nett Item :	2,040.00
Labour :	7,640.00
GST (7.00%) :	-
Total :	<b>34,868.00</b>
Less 20% :	<b>6,973.60</b>
	<b>27,894.40</b>
Lump Sum (Estimated) :	<b>27,850.00</b>

The repairer agree to repair the vehicle on a **Lump Sum Basis** with our recommendation of **SGD 27,850.00 (SGD Twenty Seven Thousand Eight Hundred and Fifty only)** and we are in the opinion the repairer would need about a **12.0** working day period to repair the vehicle.

Allied Auto Appraisal

Surveyed by

Ng Heng Chai  
Licensed Appraiser

# ALLIED AUTO APPRAISAL

RECOMMENDED PARTS					
No.	Descriptions	Condition	Qty	Repairer	Adjusted
1	BONNET	Dented	1	1,681.25	1,345.00
2	BONNET INSULATOR	Deformed	1	292.50	234.00
3	BONNET HINGE LH	Bent	1	120.00	96.00
4	BONNET HINGE RH	Bent	1	120.00	96.00
5	BONNET RUBBER	Necessary	1	205.00	164.00
6	BONNET LOCK	Bent	1	438.75	351.00
7	FRONT BUMPER TOP GARNISH WITH LOGO	Cracked	1	477.50	382.00
8	FRONT BUMPER GRILLE	Cracked	1	331.25	265.00
9	FRONT BUMPER	Deformed	1	907.50	726.00
10	FRONT BUMPER LOWER GRILLE	Cracked	1	356.25	285.00
11	FRONT BUMPER RETAINER LH	Detached	1	206.25	165.00
12	FRONT BUMPER RETAINER RH	Detached	1	206.25	165.00
13	FRONT BUMPER SPONGE	Torn	1	365.00	292.00
14	FRONT BUMPER REINFORCEMENT	Dented	1	556.25	445.00
15	FRONT SUPPORT PANEL	Bent	1	611.25	489.00
16	FRONT SUPPORT PANEL TOP GARNISH	Cut	1	387.50	310.00
17	FRONT AIR DUCT	Cut	1	397.50	318.00
18	HEADLAMP LH	Cracked	1	2,331.25	1,865.00
19	HEADLAMP RH	Cracked	1	2,331.25	1,865.00
20	AIRCON CONDENSER	Dented	1	978.75	783.00
21	RADIATOR	Dented	1	767.50	614.00
22	RADIATOR FAN COWLING	Dented	1	480.00	384.00
23	FRONT BUMPER LOWER COVER	Cut	1	330.00	264.00
24	WIPER TANK	Deformed	1	356.25	285.00
25	HORN	Dented	1	206.25	165.00
26	TAILGATE	Dented	1	2,457.50	1,966.00
27	TAILGATE LOGO	Necessary	1	118.75	95.00
28	TAILGATE "FREED" EMBLEM	Necessary	1	106.25	85.00
29	TAILGATE "HTBRID" EMBLEM	Necessary	1	81.25	65.00
30	TAILGATE WINDSCREEN MOULDING	Necessary	1	275.00	220.00
31	TAILGATE OUTER GARNISH	Cracked	1	432.50	346.00
32	TAILGATE INNER TRIM	Cracked	1	477.50	382.00
33	TAILGATE LOCK	Jammed	1	431.25	345.00
34	TAILGATE LAMP LH	Cracked	1	532.50	426.00
35	TAILGATE LAMP RH	Cracked	1	532.50	426.00
36	TAILGATE INNER POCKET HANDLE	Deformed	1	227.50	182.00
37	TAILGATE WEATHERSTRIP	Cut	1	407.50	326.00
38	REAR WINDSCREEN	Smashed	1	1,187.50	950.00
39	REAR WIPER MOTOR ASSY	Dented	1	586.25	469.00
40	REAR WIPER BLADE	Bent	1	140.00	112.00
41	REAR BUMPER	Deformed	1	907.50	726.00
42	REAR BUMPER RETAINER LH	Detached	1	160.00	128.00
43	REAR BUMPER RETAINER RH	Detached	1	160.00	128.00
44	REAR BUMPER REFLECTOR LH	Cut	1	285.00	228.00
45	REAR BUMPER REFLECTOR RH	Cut	1	285.00	228.00
46	TAILLAMP LH	Cracked	1	823.75	659.00
47	TAILLAMP RH	Cracked	1	823.75	659.00
48	TAILLAMP PANEL LH	Dented	1	317.50	254.00
49	TAILLAMP PANEL RH	Dented	1	317.50	254.00
50	REAR END PANEL	Dented	1	1,086.25	869.00
51	REAR END PANEL TOP GARNISH	Cut	1	411.25	329.00

# ALLIED AUTO APPRAISAL

## RECOMMENDED PARTS

No.	Descriptions	Condition	Qty	Repairer	Adjusted
52	SPARE TYRE PANEL	Dented	1	1,681.25	1,345.00
53	SPARE TYRE PANEL TOP BOARD	Deformed	1	398.75	319.00
54	REAR FENDER RH	Dented	1	1,361.25	1,089.00
55	REAR FENDER INNER TRIM RH	Cut	1	532.50	426.00
56	REAR FENDER INNER COWLING RH	Cut	1	390.00	312.00
57	REAR FENDER AIR VENT RH	Deformed	1	275.00	220.00
58	REAR FENDER LH	Dented	1	1,361.25	1,089.00
59	REAR FENDER INNER TRIM LH	Cut	1	532.50	426.00
60	REAR FENDER INNER COWLING LH	Cut	1	390.00	312.00
61	REAR FENDER AIR VENT LH	Deformed	1	275.00	220.00
62	CROSSMEMBER EXTENSION RH	Dented	1	502.50	402.00
63	CROSSMEMBER EXTENSION LH	Dented	1	502.50	402.00
64	REAR KEYLESS ANTENNA	Cracked	1	457.50	366.00
65	REAR EXHAUST PIPE	Bent	1	1,156.25	925.00
66	REAR EXHAUST HEAT SHIELD	Deformed	1	387.50	310.00
67	REAR EXHAUST GASKET	Cut	1	140.00	112.00
Sub Total (\$\$) :				39,356.25	31,485.00
Discount (20%) :				7,871.25	6,297.00
Total Parts (\$\$) :				<b>31,485.00</b>	<b>25,188.00</b>

## RECOMMENDED SPECIAL NETT ITEMS

No.	Descriptions	Condition	Repairer	Adjusted
1	BONNET INSULATOR CLIPS (SET)	Necessary	100.00	80.00
2	FRONT BUMPER CLIPS (SET)	Necessary	100.00	80.00
3	FRONT GRILLE CLIPS (SET)	Necessary	100.00	80.00
4	RADIATOR COOLANT	Necessary	150.00	120.00
5	AIRCON GAS TOP UP	Necessary	100.00	80.00
6	FRONT NUMBER PLATE	Dented	80.00	50.00
7	REAR BUMPER CLIPS (SET)	Necessary	100.00	80.00
8	REAR END PANEL TOP GARNISH CLIPS (SET)	Necessary	100.00	80.00
9	REAR END PANEL SEALANT	Necessary	120.00	100.00
10	REAR SPARE TYRE PANEL SEALANT	Necessary	150.00	120.00
11	REAR RH QUARTER GLASS SEALANT	Necessary	150.00	120.00
12	REAR LH QUARTER GLASS SEALANT	Necessary	150.00	120.00
13	REAR RH FENDER INNER COWLING CLIPS (SET)	Necessary	100.00	80.00
14	REAR RH FENDER INNER TRIM CLIPS (SET)	Necessary	100.00	80.00
15	REAR LH FENDER INNER COWLING CLIPS (SET)	Necessary	100.00	80.00
16	REAR LH FENDER INNER TRIM CLIPS (SET)	Necessary	100.00	80.00
17	TAILGATE INNER TRIM CLIPS (SET)	Necessary	100.00	80.00
18	TAILGATE OUTER GARNISH CLIPS (SET)	Necessary	100.00	80.00
19	REVERSE SENSOR (SET)	Shorted	500.00	450.00
			<b>2,500.00</b>	<b>2,040.00</b>

## RECOMMENDED LABOUR

No.	Descriptions	Repairer	Adjusted
1	PANEL BEATING.	3,550.00	3,350.00
2	TO REMOVE AND REFIX REAR WINDSCREEN GLASS.	200.00	150.00
3	TO REMOVE AND REFIX AIRCON & RADIATOR.	200.00	150.00
4	TO REMOVE AND REFIX REAR QUARTER GLASS.	200.00	150.00
5	TO REMOVE AND REFIX REVERSE SENSOR.	120.00	120.00
6	TO CHECK LIGHTING AND WIRING.	200.00	150.00
7	TO DO VACUUM CLEAN.	120.00	120.00
8	TO DIAGNOSTIC CHECK.	350.00	300.00



# ALLIED AUTO APPRAISAL

## RECOMMENDED LABOUR

No.		Repairer	Adjusted
9	TOWING CHARGE.	200.00	150.00
10	TO SPRAY PAINTING.	3,200.00	3,000.00
		<b>8,340.00</b>	<b>7,640.00</b>

## COST OF CLAIMS

	Repairer	Adjusted
1 TOTAL PARTS	31,485.00	25,188.00
2 TOTAL NETT ITEMS	2,500.00	2,040.00
3 LABOUR & SPRAY	8,340.00	7,640.00
	Gross Total (S\$) :	42,325.00 34,868.00
	GST 7.00% (S\$) :	- -
	Total Amount (S\$) :	<b>42,325.00 34,868.00</b>

# ALLIED AUTO APPRAISAL



# ***ALLIED AUTO APPRAISAL***



# ***ALLIED AUTO APPRAISAL***





# ***ALLIED AUTO APPRAISAL***



# ***ALLIED AUTO APPRAISAL***





# ***ALLIED AUTO APPRAISAL***



# ***ALLIED AUTO APPRAISAL***



# ***ALLIED AUTO APPRAISAL***





# ***ALLIED AUTO APPRAISAL***



# ***ALLIED AUTO APPRAISAL***



# ***ALLIED AUTO APPRAISAL***

