

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0464/2023/EQ  
**DATE** : 12-May-23  
**WIP** : 20453

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/6/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR CHUA YI HSIUNG GARY  
**ADDRESS** : 9 LORONG LEW LIAN  
#09-06, FOREST WOODS  
SINGAPORE 536494  
**TELEPHONE** : HP +65 98292883  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900014314-03  
**VEHICLE NO** : **SMH 8457 S**  
**MODEL CODE** : AUDI A3 SEDAN 1.0 TFSI  
**MODEL YEAR** : 11/2/2019  
**ENGINE NO** : CHZ C26234  
**CHASSIS NO** : WAUZZZ8V7K1014358  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 9-May-23  
**PLACE OF ACCIDENT** : TANGLIN ROAD OPPOSITE GLENEAGLES HOSPITAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 8457 S**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE REAR FENDER RENEWAL.	S/N \$	600.00	
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 4,280.00</b>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 8457 S**

S/N	NATURE OF JOBS	ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, END PANELLING, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL AND DOOR ENTRANCES.	\$	5,000.00	
9	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 14,652.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 8457 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,455.00	
2	REAR BUMPER GUIDE SECTION - RH	1	\$ 19.00	
3	REAR WHEEL HOUSING LINER ADAPTER - RH	1	\$ 45.00	
4	REAR BUMPER REFLECTOR - RH	1	\$ 49.00	
5	REAR BUMPER GUIDE SECTION - RH	1	\$ 79.00	
6	REAR SIDE PANEL - RH	1	\$ 4,706.00	
7	REAR WINDOW	1	\$ 961.00	
8	REAR QUARTER WINDOW - RH	1	\$ 773.00	
9	WINDOW PRIMER	2	\$ 47.00	
10	REAR FUEL INSERT	1	\$ 106.00	
11	REAR WHEEL HOUSING LINER - RH	1	\$ 281.00	
12	REAR ALUMINIUM RIM	1	\$ 1,380.00	
13	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
14	ACRYLIC SEALANT	S/N	\$ 180.00	
15	CAVITY WAX	S/N	\$ 140.00	
16	METAL FILLER POWDER	S/N	\$ 280.00	
17	STONE CHIP	S/N	\$ 180.00	
18	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
19	1/4 GLASS SEALANT	S/N	\$ 100.00	
20	SUNDRIES		\$ 600.00	
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 12,585.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 14,652.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 27,237.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT