

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2306-376-TG
DATE : 5-Jun-2023
VEHICLE REG. NO. : SCY6862Y
VEHICLE MAKE : TOYOTA SIENTA 1.5 CVT STD
CHASSIS NO : MHFZ28H3700025190
DATE OF REG : 24/5/2017

TO Motor Claim Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

FOR SURVEYOR

*RASUL - 4p 900ws68
6 days / L/S 07/06/23 @ 1250
Resy after repv*

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>SCA</i>	1	\$ 559.85	\$ 559.85
2	Front Bumper Side Retainer RH ?	1	\$ 104.98	\$ 104.98
3	Front Bumper Garnish RH <i>SCA</i>	1	\$ 163.30	\$ 163.30
4	Front Fender RH <i>bt</i>	1	\$ 574.01	\$ 574.01
5	Front Fender Innershield RH ?	1	\$ 248.28	\$ 248.28
6	Front Door RH <i>repv</i>	1	\$ 1,289.65	\$ 1,289.65
7	Front Door Side Mirror Assy RH <i>repv CR</i>	1	\$ 588.18	\$ 588.18
8	Front Headlamp RH <i>SCA</i>	1	\$ 899.75	\$ 899.75
9	Front Rim RH <i>cut</i>	1	\$ 754.35	\$ 754.35
Parts Less 20%				\$ (1,036.47)
Total Spare Parts				\$ 4,145.88
SPECIAL NETT				
10	Front Bumper Clips <i>SCA</i>	10	\$ 5.00	\$ 30 50.00
Total Special Nett				\$ 50.00
LABOUR				
11	Remove, Refit and Repair Affected Accident Parts	1	\$ 800.00	\$ 800.00 <i>500</i>
12	Spray Painting Front Bumper, Front Fender RH, Front Door RH	1	\$ 800.00	\$ 800.00 <i>600</i>
13	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00 <i>X</i>
14	Perform 4 Wheel Alignment	1	\$ 70.00	\$ 70.00 <i>60</i>
15	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00 <i>30</i>
Total Labour				\$ 1,820.00
Amount Before Excess				\$ 6,015.88
Add GST @ 8%				481.27
Total Amount Payable				\$ 6,497.15

Estimate prepared by: JAMES TAN

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: