



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8660S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	ROCKER COVER GARNISH LH	TO REPAIR SEE LABOUR	732.80	-
	LESS 20% DISCOUNT		-146.56	-
			586.24	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	RR DOOR COMFORT APP LOGO LH (SN)	NECESSARY	80.00	80.00
1	RENEW ADVERTISEMENT STICKER (SN)	NECESSARY	200.00	200.00
			280.00	280.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF ROCKER COVER GARNISH LH.		300.00	280.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TRANSFER OF FRT/RR DOOR.	NOT NECESSARY	120.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
			1,080.00	780.00
	<b>GRAND TOTAL</b>		<b>1,946.24</b>	<b>1,060.00</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,060.00</b>

Report Ref No. NS/INC23005745/Tvp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.