

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA8660S

Make : HYUNDAI

Model : I-40

Date: 06/06/23

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	ROCKER COVER GARNISH LH			\$ Rp 732.80
				\$ 732.80
				\$ 146.56
				\$ 586.24
				\$ 80.00
				\$ 200.00
				\$ 280.00
				\$ 300.00
				\$ 600.00
				\$ 120.00
				\$ 60.00
				\$ 1,080.00
				\$ 1,946.24

SUB TOTAL
 LESS 20%
 DISCOUNTED TOTAL
 RR DOOR COMFORT APP LOGO LH
 RENEW ADVERTISEMENT STICKER
 Labour Charge
 PANEL BEATING *Repair fender, rear LH door -*
 SPRAY PAINTING CHARGE
 TRANSFER OF FRT/ RR DOOR
 TUFF KOTE
 TOTAL LABOUR
 ESTIMATE TOTAL

280
 780
 \$1060
 03 days

Net
 Net
 Net
 280
 500
 X n
 X n

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjhi 97495749
 up 6/6/23 2315pm
 03 days
 Resurvey after repair
 Tanjhi e/transportation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer