

**SMRT Accident Vehicle Repair Estimates**

SMRT Auton  
60 Woodland  
FAX Number  
Estimator Tel  
Accident Rep

Date Genera

User ID

**Section A - Accident Details**

Registration Number	SHB271D
Case Reference Number	TAX/06/23/2009
Registration Date	29/12/21
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	SAAD BIN MIDI
Type of Accident	Side Swipe
Accident Date and Time	6/6/23 12:30 PM
Accident Reported Date and Time	6/6/23 1:30 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118602
Special Instruction to ARC,if any	RIGHT REAR
Prepared Date and Time	6/6/23 3:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,800.00	\$0.00
Total Spray Cost	\$1,514.00	\$0.00
Total Spare Part Cost	\$6,676.31	\$0.00
Total Other Cost	\$2,055.00	\$0.00
<b>TOTAL COST</b>	<b>\$12,045.31</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	10.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	06/06/2023 3:29 PM	
Signature		<input type="checkbox"/> <i>Ramal - Hy 90010068 4 days p/p</i>
Remarks		<i>07/06/23 P/6/0 Rez 5k part email: ragsul@kkauto.com</i>

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

SMRT Auton  
60 Woodland  
FAX Number  
Estimator Tel  
Accident Rep

Date Genera

User ID

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicabl
TO REPAIR REAR PORTION RH	\$1,800.00	400 ✓
<b>Total Labour</b>	<b>\$1,800.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO RESPRAY REAR BUMPER	\$428.00	220 ✓
TO RESPRAY RIM	\$230.00	50 ✓
TO RESPRAY REAR FENDER RH	\$428.00	220 ✓
TO RESPRAY RH REAR DOOR	\$428.00	220 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,514.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO WASH AND VACUUM	\$60.00	X 11
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X 11
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	30 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	50 ✓
TO REMOVE AND REFIT TYRE	\$120.00	X 11
TO TRANSFER DOOR MECHANISM	\$120.00	60 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	X 11
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	X 11
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	X 11
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	X 11
TO REPLACE SUNDRY PARTS	\$100.00	20 ✓
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	150 ✓
ISOLATED OF (EV) (NET)	\$150.00	150 ✓
<b>Total Other Costs</b>	<b>\$2,055.00</b>	

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		10718213	SENSOR ASM-TIRE PRESS IND	1.00	\$82.99	10.00	\$74.69	Replace	X 11
		10560908	MODULE ASM-TIRE PRESS MON CONT	1.00	\$125.53	10.00	\$112.98	Replace	X 11
		10465727	BRACKET ASM-RR BPR FASCIA SI-RH	1.00	\$29.85	10.00	\$26.87 ✓	Replace	111 ✓
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	Refit ✓
		10626941	LINER ASM-RR W/H PNL - RH	1.00	\$85.48	10.00	\$76.93	Replace	X 11
		10380138-SEPP	DOOR ASM-RR SI -RH	1.00	\$2,185.04	10.00	\$1,966.54 ✓	Replace	bl ✓
		10393841	FILM-RR S/D FRM - RH	1.00	\$9.88	10.00	\$8.89 ✓	Replace	111 ✓
		10393843	FILM-RR S/D FRM - RH	1.00	\$9.88	10.00	\$8.89 ✓	Replace	111 ✓
		10359003	FINISHER-RR BPR - RH	1.00	\$47.42	10.00	\$42.68	Replace	X 11
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	1.00	\$46.08	10.00	\$41.47	Replace	X 11
		10322238	WINDOW ASM-QTR - RH	1.00	\$251.47	10.00	\$226.32	Replace	X 11
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	X 11
			STICKER ELECTRIC ( LOGO	1.00	\$21.60	0.00	\$21.60 ✓	Replace	111 ✓
		10509505	BEARING ASM-RR WHL	1.00	\$335.40	10.00	\$301.86	Replace	X 11

## SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera

User ID

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		10751826	BEAM ASM-RR SUSP EQLZR	1.00	\$1,649.54	10.00	\$1,484.59	Replace	Xm
		10317983	Wheel REAR RH	1.00	\$618.07	10.00	\$556.26	Replace	Repair
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Xm
		10720690CC-SEPP	PANEL-BODY SI OTR RR-R	1.00	\$977.08	10.00	\$879.37	Replace	Repair
<b>Total</b>					<b>\$7,397.53</b>		<b>\$6,676.31</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ch
<b>Total</b>									

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: