

ASS. REC. BY:

REF: AIS / 23 005755/Kp

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Covan His

of 80211

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 32k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

12/26

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: EM 8391R Yr Regn: 02, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volvo S60 c.c. 1984

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 75788 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YVIRS494972625940

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 2 mm

R/Bal. 2 mm

L/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 5/6/23

D.O.I. 7/6/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

& rest

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>EM not ready, no parts at local market, maybe part by part. O/A what @ 19,671.00</u>
<u>23/6</u>	<u>21 Rep @ 52001 Covan 27/6/23</u>

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

Survey Fee:

2) _____

Add Fee: : Site Insp (\$ _____)

Transportation

Report Format :

: Interview (\$ _____)

S - RS. SI

Lump Sum / I.B.I: (\$ _____)

: Tech Invs (\$ _____)

Fuel

: Weekend (\$ _____)

Others

TOTAL

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A
 #02-03 AMK AUTOPOINT 568047
 Tel No. : 64837111 Fax No. : 64837221
 E-Mail : guanhinmotor@yahoo.com
 Buss. Reg. No. : 06035200X PAYNOW

Not Authorized
11 Rm @ 5200p
Assembly After Repair
4 days

ALLIANZ INSURANCE SINGAPORE PTE LTD
 70 ROBINSON ROAD
 #09-01 SINGAPORE 068897

Attention : Motor Claim Department
 Contact : 67143369

Estimate : ES000981

Date : 05/06/2023
 Vehicle Num. : EM 8391 R
 Make/Model : VOLVO S60 2.0 T-2006
 Chassis/Eng# : YV1RS494972625940/B5204T4067085
 Accident Date : 05/06/2023
 Claim No. :
 Reference :
 Policy No. : (12/02/2007)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- LIST ITEMS :
1. 1 REAR BOOT
 2. 1 BOOT LIP OUTER GARNISH *728*
 3. 1 REAR BUMPER *1850*
 4. 2 REAR BUMPER BRACKET *1900*
 5. 1 FRONT BUMPER
 6. 1 GRILLE
 7. 2 REAR BUMPER PROTECTOR
 8. 2 REAR BUMPER MOULDING
 9. 1 RH TAIL LAMP
 10. 1 'VOLVO' EMBLEM
 11. 1 'S 60' EMBLEM
 12. 1 '2.0 T' EMBLEM

<i>R</i>	2,900.00	X
<i>CM</i>	1,650.00	✓
<i>Bur</i>	2,200.00	✓
<i>R</i>	300.00	X
<i>Bur</i>	2,100.00	✓
<i>Sm</i>	1,300.00	X
<i>R</i>	400.00	X
<i>200.00</i>	380.00	✓
<i>190.00</i>	380.00	✓
<i>CM</i>	520.00	✓
<i>RM</i>	50.00	✓
<i>RM</i>	45.00	✓
<i>RM</i>	42.00	✓
<hr/>		
	11,887.00	

List Total S\$:

- SPECIAL NETT ITEMS :
1. 1 SET REVERSE SENSOR
 2. 1 SET FRONT NO PLATE & FRAM

<i>Sm</i>	282.00	X
<i>CM</i>	50.00	45.00
<hr/>		
	332.00	


Special Nett Total S\$:

- LABOUR :
- REMOVE & FIX BACK REAR BOOT, BUMPER, TAIL LAMP
 - STRIGHTEN REAR PANEL
 - TRANSFER BOOT LIP ASSY
 - REMOVE & FIX BACK REVERSE SENSOR
 - SPRAY PAINTING FRT AND REAR BUMPER AND BOOT AND PANEL

900.00	<i>600</i>
150.00	<i>50</i>
150.00	<i>50</i>
1,000.00	<i>800</i>
<hr/>	
2,200.00	

Labour Total S\$:

Total S\$: **14,419.00**



for GUAN HIN MOTOR WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

E & O.E.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: