

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Insurance Singapore Pte.Ltd.

Policy No: Third Party

Accident Date : 21.05.2023

Date: 05.06.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Hyundai Avante" Reg. No SMQ6972J Claiming Against Your Insured Reg. No. SNJ2164D			
1pc	Rear Bumper	4.50	CM 527.00 —
12pcs	Rear Bumper Clips		na 54.00 —
1pc	Rear Bumper Top Retainer RH		nit 30.50 —
1pc	Rear Bumper Sponge		170.00 7
1pc	Rear Bumper Reinforcement		340.00 7
1pc	Rear Bumper Lamp RH (Reverse)		na 211.00 —
1pc	Rear Bumper Corner Retainer		CM 112.00 —
1pc	Rear Bumper Center Cover		361.00 7
1pc	Rear Bumper Lower Splash Guard RH		47.00 7
1pc	Taillamp RH (LED)		CM 1,154.00 —
1pc	Taillamp Gasket		na 45.00 —
1pc	Rear Fender Lower Air Vent RH		CM 78.60 —
	Less 10%		3,130.10
			313.01
			2,817.09
	Labour Charge - Panel Beating, Repairing of End Panel, Rear O/S Fender & Part Replacement		500.00 2001
	To Respray Affected Areas		600.00 4001
		Total :	3,917.09

Not with out
Return By painting
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: