



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3451E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	700.00	700.00
1	SIDE DOOR	TO REPAIR SEE LABOUR	800.00	-
1	TAIL LIGHT	SCRATCHED	400.00	400.00
	LESS 25% DISCOUNT		-	-275.00
			1,900.00	825.00
	<u>SPECIAL NETT ITEMS</u>			
1	SPORT RIM (SN)	SCRATCHED	700.00	400.00
			700.00	400.00
	<u>LABOUR</u>			
	PAINTING.		800.00	600.00
	LABOUR. INCLUSIVE OF THE REPAIR OF SIDE DOOR.		400.00	300.00
			1,200.00	900.00
	GRAND TOTAL		3,800.00	2,125.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/LIP23005763/Rnp3e2

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,269.00=NETT VALUE: \$3,731.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.